

DEPARTMENT OF ENERGY

National Nuclear Security Administration Los Alamos Site Office Los Alamos. New Mexico 87544



NOV 17 2004

John Kieling, Manager RCRA Permits Management Program Hazardous Waste Bureau 2905 Rodeo Park Drive East, Building 1 Santa Fe, NM 87505-6303

Dear Mr. Kieling:

Subject:

Transmittal of the U.S. Department of Energy-National Nuclear Security

Administration (DOE-NNSA)/University of California (UC) November 2004

Class 1 Permit Modifications, Los Alamos National Laboratory (LANL) Hazardous

Waste Facility Permit

The purpose of this letter is to transmit to the New Mexico Environment Department (NMED), the DOE-NNSA/UC November 2004 Class 1 Permit Modifications (LA-UR-04-7744) to the Hazardous Waste Facility Permit. These modifications were overlooked within the last Class 1 permit modification submittal on October 4, 2004.

The redline-strikeout sections within this submittal make changes to Module II, Module III, Attachment F, and Attachment G of the permit. These changes have been made to incorporate two Class 1 permit modifications. The first modification is the correction of a typographical error that was located within Table 2-2 of Module II. The modification to the language within Module III, Attachment F, and Attachment G have been made incorporating an approved change to a unit made pursuant to a change during interim status under Code of Federal Regulations, Title 40, § 270.42.

Included herein are three hard copies and one electronic copy of this submittal. The electronic copy includes files containing editing marks as well as a clean version of each of the sections modified. In you have any comments or questions regarding this submittal please contact Gene Turner at (505) 667-5794 or Jack Ellvinger, UC at (505) 667-0633.

Sincerely,

Edwin L. Wilmot

Manager

EM:5GT-017

Enclosures

cc w/enclosure:

Laurie King, Chief (6PD-N)
New Mexico/Federal Facilities Section
Environmental Protection Agency, Region 6
1445 Ross Avenue, Suite 1200
Dallas, TX 75202-2733

cc w/out enclosure:

James Bearzi, Chief Hazardous Waste Bureau New Mexico Environment Department 2905 Rodeo Park Drive East, Building 1 Santa Fe, NM 87505-6303

- G. Turner, EM, LASO
- J. Ordaz, EM, LASO
- J. Stetson, PWT, LASO
- D. Christensen, FWO-SWO, MS-J595
- D. McLain, FWO-WFM, LANL, MS-J593
- E. Louderbough, LC-ESH, LANL, MS-A187
- R. Lechel, FWO-WFM, LANL, MS-J593
- J. Ellvinger, RRES-SWRC, LANL, MS-K490

Document: Date: Class 1 Permit Modifications November 2004

CERTIFICATION

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Kenneth M. Hargis Division Leader

Environmental Stewardship Division

Los Alamos National Laboratory

Date Signed

Edwin L. Wilmot

Manager, Los Alamos Site Office

National Nuclear Security Administration

U.S. Department of Energy

Owner/Operator

Date Signed

LA-UR-04-7744

November 2004

November 2004 Class 1 Permit Modifications Los Alamos National Laboratory Hazardous Waste Facility Permit

Prepared by:

Los Alamos National Laboratory Environmental Stewardship Division Solid Waste Regulatory Compliance Group (ENV-SWRC) Los Alamos, New Mexico 87545

MODULE II GENERAL FACILITY CONDITIONS

II.A. DESIGN AND OPERATION OF THE FACILITY

The Permittee shall maintain and operate the facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release to air, soil, or surface water of hazardous waste constituents which could threaten human health or the environment.

II.B. REQUIRED NOTICE

- 1. <u>Foreign Wastes</u> This permit does not allow the Permittee to accept wastes from a foreign source. If the Permittee is to receive hazardous waste from a foreign source, he shall apply for and receive a permit modification in accordance with HWMR-5, as amended 1989, Part IX, 40 CFR Section 270.41 or 270.42, if appropriate, prior to accepting such waste.
- 2. Off-Site Wastes This permit does not allow the Permittee to accept wastes from an off-site source. "Off-site source" refers to wastes generated by sources other than the Permittee or its contractor(s) operating on-site. For the purposes of this permit, wastes generated by the Permittee at Technical Area 57, the Fenton Hill site, and waste generated through investigation of Potential Release Sites (PRS) and/or Solid Waste Management Units (SWMU) listed in Table II-3 (at the end of Module II); or the waste generated through the restoration of the PRS/SWMU sites listed in Table II-3 may be accepted for storage or treatment if all such waste is properly manifested in accordance with permit paragraph II.J. below. Waste or contaminated residuals of waste associated with off-site treatment of those waste streams originally generated by the Permittee and subsequently managed or treated by the off-site facilities listed in Module II, Table 2-2, may be accepted for storage or treatment if all such waste is properly characterized and manifested in accordance with permit paragraph II.J. If the Permittee is to receive hazardous waste from an off-site source, other than those off-site sources listed in Table II-3 and Table 2-2, he shall apply for and receive a permit modification in accordance with HWMR-5, as amended 1989, Part IX, 40 CFR Section 270.42, if appropriate, prior to accepting such waste.

II.C. WASTE ANALYSIS

- 1. <u>Waste Analysis Plan</u> The Permittee shall follow the procedures described in Permit Attachment A.
- 2. Quality Assurance The Permittee shall verify its waste analysis as part of a written quality assurance program. The quality assurance program shall be in accordance with current accepted practices such as specified in Test Methods for Evaluating Solid Waste:Physical/Chemical Methods SW-846, or equivalent methods approved by the Secretary; and at a minimum ensure that the Permittee maintains proper functional instruments, uses approved sampling and analytical methods, verifies the validity of sampling and analytical procedures, and performs correct calculations. The Permittee will notify any contract laboratory of the requirements of this section and permit.

- 3. <u>Waste Segregation</u> The Permittee shall keep available at at the facility, in accordance with EPA-600/2-80-076, <u>A Method of Determining the Compatibility of Hazardous Waste</u>.
- 4. <u>Annual Verification</u> The Permittee shall annually, by the anniversary date of each quarterly report, verify the accuracy and currency of the waste stream determination made in Permit Attachment I.

II.D. SECURITY

The Permittee shall comply with the security provisions of HWMR-5, as amended 1989, Part V, 40 CFR Section 264.14.

II.E. INSPECTION REQUIREMENTS

1. <u>Inspection Plan</u> The Permittee shall follow Permit Attachment B and the inspection requirements in Modules III through VII. The Permittee shall remedy any deterioration or malfunction of equipment or structure discovered by an inspection as required by HWMR-5, as amended 1989, Part V, 40 CFR Section 264.15(c). Inspection log sheets may be revised by the Permittee and submitted to the Secretary for inclusion in this permit by permit modification in accordance with HWMR-5, as amended 1989, Part IX, 40 CFR Section 270.42.

2. Facility Release Inspection

- a. The Permittee shall take surface water samples and analyze for metals, volatile and both acid- and base-neutral semivolatile organic hazardous waste constituents in accordance with Table II-2 annually at the sample locations in Table II-1. See Figure 9.
- b. The sampling and analysis shall be done using EPA-approved procedures as published in the latest issue of SW-846.
- c. Analysis of Variance (ANOVA) statistical procedures as promulgated in 53 FR 39720 (October 11, 1988) shall be used to compare data between up-gradient and down-gradient stations.
- d. Records of this inspection shall be kept in accordance with permit paragraph II.K.1.a. below. All analytical results will be recorded and reported. Reports shall be on the form provided in Figure 10.
- e. Reports of releases detected by this inspection shall be made in accordance with permit paragraph II.K.2.c. below.
- f. In the event water samples cannot be obtained at one or more sites, the attempt to obtain samples will be documented in the facility record and the Secretary notified in writing within 30 days of each unsuccessful attempt.

II.F. PERSONNEL TRAINING

The Permittee shall conduct personnel training as required by HWMR-5, as amended 1989, Part V, 40 CFR Section 264.16. This training program shall follow Permit Attachment C, which shall be updated by the Permittee whenever necessary so as to remain current and accurate. A dated copy of the revised training program will be submitted to the Secretary for the permit files and permit modification in accordance with HWMR-5, as amended 1989, Part IX, 40 CFR Section 270.42 prior to its implementation. The Permittee shall maintain training documents and records, as required by HWMR-5, as amended 1989, Part V, 40 CFR Section 264.16(d) and (e).

II.G. REQUIREMENTS FOR IGNITABLE, REACTIVE, OR INCOMPATIBLE WASTE

The Permittee shall comply with the requirements of HWMR-5, as amended 1989, Part V, 40 CFR Section 264.17.

II.H. PREPAREDNESS AND PREVENTION

- 1. <u>Required Equipment</u> At a minimum, the Permittee shall equip the facility with the equipment set forth in Permit Attachments B. and D or the functional equivalent.
- 2. <u>Testing and Maintenance of Equipment</u> The Permittee shall test and maintain the equipment specified in permit paragraph II.H.1. above annually or more often if necessary to assure its proper operation in time of emergency.
- 3. <u>Access to Communications or Alarm System</u> The Permittee shall maintain access to the communications or alarm system(s) as required by HWMR-5, as amended 1989, Part V, 40 CFR Section 264.34.
- 4. Required Aisle Space The Permittee shall maintain aisle space as required by HWMR-5, as amended 1989, Part V, 40 CFR Section 264.35. The minimum aisle shall be twenty four inches. All containers in storage shall be accessible for inspection.

II.I. CONTINGENCY PLAN

- 1. <u>Implementation of Plan</u> The Permittee shall immediately carry out the provisions of Permit Attachment D. whenever there is an unplanned fire, explosion, or unpermitted release of hazardous waste or hazardous constituents which threatens or could threaten human health or the environment.
- 2. <u>Amendment of the Plan</u> The Permittee shall review, as required by HWMR-5, as amended 1989, Part V, 40 CFR Section 264.54., and immediately amend if necessary, the Contingency Plan.
- 3. <u>Copies of the Plan</u> The Permittee shall comply with the requirements of HWMR-5, as amended 1989, Part V, 40 CFR Section 264.53. A dated copy of any amended Contingency Plan will be submitted to the Secretary for the permit files and permit modification in accordance with HWMR-5, as amended 1989, Part IX, 40 CFR Section 270.42 prior to its implementation.

4. <u>Emergency Coordinator</u> The Permittee shall comply with the requirements of HWMR-5, as amended 1989, Part V, 40 CFR Section 264.55 concerning the emergency coordinator.

II.J. MANIFEST SYSTEM

The Permittee shall comply with the manifest requirements of HWMR-5, as amended 1989, Part V, 40 CFR Sections 264.71 and 264.72 for any hazardous wastes received from or shipped off-site by the Permittee for treatment, storage or disposal.

II.K.RECORD KEEPING AND REPORTING

- 1. <u>Facility Operating Record</u> The Facility Operating Record maintained pursuant to HWMR-5, as amended 1989, Part V, 40 CFR Section 264.73 shall be maintained in such manner that any information required to be in the record shall be readily available to an inspector. Readily available means that, upon request by an inspector, the Permittee can provide the requested information within 24 hours or before the end of the inspection, whichever is less; or upon a schedule designated by the inspector.
 - a. In accordance with HWMR-5, as amended 1989, Part IX, 40 CFR Section 270.30(j), the Permittee shall maintain at the facility until the end of the last closure period, a written record of waste and decontamination wash-water analyses. The following information shall be recorded:
 - (i) The dates, exact place, and times of sampling or measurements;
 - (ii) The individual who performed the sampling or measurements;
 - (iii) The dates analyses were performed;
 - (iv) The individuals or off-site laboratory who performed the analyses;
 - (v) The analytical techniques or methods used; and
 - (vi) The results of such analyses. The results shall include range, mean, standard deviation and detection limits as applicable to facilitate data analysis.
 - b. The Permittee shall maintain pursuant to HWMR-5, as amended 1989, Part V, 40 CFR Section 264.73(b) at the facility until the end of the last closure period, a written record of waste disposal activities. Current EPA approved nomenclature and codes shall be used where appropriate. The following information shall be recorded:
 - (i) Waste Source;
 - (ii) Waste Description;
 - (iii) Waste Quantity;

- (iv) Current Storage Location; and
- (v) Disposal. Properly completed hazardous waste manifests will suffice for wastes shipped off-site.
- c. The Permittee shall maintain at the facility a written record of Contingency Plan implementation reports. The record shall contain at least the information required in permit paragraph II K.2.b. below. These records shall be kept until the end of the last closure period.
- d. The Permittee shall keep at the facility a written record of all inspections conducted in accordance with Permit Attachment B. and permit paragraph II.E. above. These records shall be maintained for a minimum period of three years from the date of the inspection. Records of inspections leading to corrective action shall be retained for three years after the corrective action taken as a result of the inspection.
- e. The Permittee shall keep at the facility training documents and records as required by HWMR-5, as amended 1989, Part V, 40 CFR Sections 264.16(d) and 264.1 6(e), and Permit Attachment C. Records of training shall be kept on all current employees and for three years after an employee leaves the facility owner's or operator's employ.
- f. The Permittee shall maintain at the facility a copy of all biennial reports submitted in accordance with permit paragraph II.K.2. below. These copies shall be kept until the end of the last closure period.
- g. The Permittee shall keep sufficient monitoring records and documentation to demonstrate compliance with this permit. Records unique to one activity may be kept in the vicinity of that activity, subject to the availability requirement in permit paragraph II.K.1. above.
- h. In accordance with HWMR-5, as amended 1989, part V, 40 CFR Section 264.74(b), the retention period for all records required by this permit is extended automatically during the course of any unresolved enforcement action regarding the facility, or as directed by the Secretary.

2. Reports

- a. The Permittee shall comply with the Biennial Report requirements of HWMR-5, as amended 1989, Part V, 40 CFR Section 264.75.
- b. In accordance with HWMR-5, as amended 1989, Part IX, 40 CFR Section 270.30(l)(6), the Permittee shall report to the Secretary any noncompliance with the permit which may endanger human health or the environment. Any such information shall be reported orally within 24 hours from the time the Permittee becomes aware of the circumstances. This report shall include the following:
 - (i) Information concerning the release of any hazardous waste which may endanger public or private drinking water supplies.

- (ii) Information concerning the release or discharge of any hazardous waste, or of a fire or explosion at the facility, which could threaten the environment or human health. The description of the occurrence and its cause shall include:
 - (a) Name, address, and telephone number of the owner or operator;
 - (b) Name, address, and telephone number of the facility;
 - (c) Date, time, and type of incident;
 - (d) Name and quantity of materials involved;
 - (e) The extent of injuries, if any;
 - (f) An assessment of actual or potential hazard to the environment and human health outside the facility, where this is applicable; and
 - (g) Estimated quantity and disposition of recovered material that resulted from the incident.

The 24-hour report shall be made by calling (505) 827-4358 during normal duty hours or (505) 827-9329, the 24-hour emergency line.

c. The Permittee shall provide to the Secretary within five (5) working days of the time the Permittee becomes aware of the circumstances, a written report on the event(s) reported orally in permit paragraph II.K.2.b. above. The written submission shall contain a description of the noncompliance and its cause; the periods of noncompliance, including exact dates and times; whether the noncompliance has been corrected; and if not, the anticipated time it is expected to continue; and steps taken or planned to reduce, eliminate, and prevent recurrence of the noncompliance. The Permittee need not comply with the five-day written notice requirement if the Secretary waives the requirement and the Permittee submits a written report within fifteen (15) calendar days

of the time the Permittee becomes aware of the circumstances. The written report shall be submitted by certified mail to:

Secretary
New Mexico Environment Department
1190 St. Francis Drive, P.O.Box 26110
Harold Runnels Building
Santa Fe, NM 87502-6110

d. In accordance with HWMR-5, as amended 1989, Part IX, 40 CFR Section 270.30(l)(10), the Permittee shall report all other instances of noncompliance, not otherwise required to be reported above, in the annual Environmental Surveillance Report. The reports shall contain the information listed in permit paragraph II.K.2.b. above.

II.L. CLOSURE

The provisions of this permit section apply to individual units for partial closure of the facility, as well as total closure of the entire facility. Closure of one unit may or may not affect the remaining units. The impact of such sequential or partial closure may depend on the sequence and circumstances in existence at the time of closure. The Secretary may direct or the Permittee may request appropriate revisions to the closure plan at that time.

- 1. <u>Performance Standard</u> The Permittee shall close the facility as required by HWMR-5, as amended 1989, Part V, 40 CFR Section 264.111 and in accordance with each closure plan, Permit Attachment E.
- 2. <u>Amendment of Closure Plans</u> The Permittee shall amend each closure plan in accordance with HWMR-5 as amended 1989, Part V, 40 CFR Section 264.112(c) whenever necessary.
- 3. <u>Notification of Closure</u> The Permittee shall notify the Secretary at least 60 days prior to the date he expects to begin closure under any Permit Attachment E. closure plan.
- 4. <u>Time Allowed For Closure</u> After receiving the final volume of hazardous waste, the Permittee shall treat or remove from site all hazardous waste in accordance with the schedule specified in the closure plan. After receiving the final volume of hazardous waste, the Permittee shall complete closure activities in accordance with the schedule specified in the closure plan.
- 5. <u>Disposal or Decontamination of Equipment</u> The Permittee shall properly dispose of or decontaminate all facility equipment, structures, and soils, as required by the closure plan.
- 6. <u>Certification of Closure</u> The Permittee shall certify that the facility has been closed in accordance with the specifications in the closure plan.

II.M. MOVEMENT RESTRICTION

The Permittee shall not transport bulk liquid hazardous wastes in quantities per container in excess of 110 gallons over public roads between the hours of 7:00 AM to 8:30 AM, 12:15 PM to 1:30 PM or 4:00 PM to 5:45 PM on normal duty days. Off-site transportation under U.S. Department of Transportation regulations by EPA-registered transporters is not subject to this restriction. On-site transportation of wastes generated as a result of an emergency cleanup in accordance with Permit Attachment D are not subject to this restriction.

II.N. Spills

The Permittee shall take corrective action, as required by Section 74-4-4.2B NMSA 1978, (as amended 1989), for all releases of hazardous wastes or constituents from any solid waste management unit at his facility. Corrective action may include, but shall not be limited to, the following: decontamination and/or removal of all releases, spills and leaks; immediate cleanup of release or spillage of hazardous wastes, or constituent residue or listed chemicals which become wastes; prevention of surface-water or ground-water contamination which could result from a release or spill; and, cleanup of any surface-water or ground-water contamination which results from a release or spill.

TABLE II-1
ENVIRONMENTAL MONITORING LOCATIONS

STATION	N-S Coordinate (LANL Grid)	E-W Coordinate (LANL Grid)	Map No.
Y 11 B	21105	***************************************	
Los Alamos Reservoir	N105	W090	7
Frijoles	S280	E180	9
Canada del Buey	N010	E150	46
Water Canyon at Beta	S090	E090	48
Acid Weir	N125	E070	49
Pueblo - 2	N120	E155	51
Pueblo - 3	N085	E315	53
DPS - 1	N090	E160	57
SCS - 2	N060	E140	66
Pajarito Stream	S180	E140	35
Ancho Stream	S295	E340	36
Frijoles Stream	S365	E235	37
Pajarito Canyon (PCO-3)	S098	E293	104
LAO-4.5	N065	E270	64
MCO-3	N040	E110	69
MCO-8	N030	E190	74
Basalt Spring	N065	E395	56

TABLE II-2 SAMPLING PARAMETERS

TOTAL METALS	ORGANICS	OTHER
Arsenic Barium Cadmium Chromium Lead Mercury Selenium Silver Nickel Beryllium Copper Zinc Iron	Halogenated volatile organics Nonhalogenated volatile organics Acid-extractable semivolatile organics Base-neutral extractable semivolatile organics Phenols	Cyanide pH

All methods are as published in US EPA SW-846, 3rd Edition or later.

If any metal's total concentration exceeds that metal's standard for Toxicity Characteristic Leachate Procedure (TCLP) toxicity, a determination of the TCLP toxicity concentration for that metal will be performed. Both data will be recorded and reported.

TABLE II-3

List of Off-Site Potential Release Site (PRS) and/or Off-Site Solid Waste Management Units (SWMU) that may have Investigative Derived Waste (IDW) or Remediation Waste (RW) brought on to Los Alamos National Laboratory.

PRS/SWMU Number	Technical Area	Operational Unit	Unit Type
00-003	0	1071	Container Storage
00-005	0	1071	Landfill
00-011(a)	0	1071	Mortar Impact Area
00-011(c)	0	1071	Mortar Impact Area
00-011(d)	0	1071	Mortar Impact Area
00-011(e)	0	1071	Mortar Impact Area
00-012	0	1071	Underground Storage Tank
00-016	0	1071	Firing Range
00-017	0	1071	Waste Lines
00-018(a)	0	1071	Pueblo Waste Water Treatment Plant
00-019	0	1071	Waste Water Treatment Plant
00-028(a)	0	1071	Effluent Discharge
00-028(b)	0	1071	Effluent Discharge
00-030(a)	0	1071	Septic System
00-030(b)	0	1071	Septic System (6th St.)
00-030(g)	0	1071	Septic System
00-030(1)	0	1071	Septic System
00-030(m)	0	1071	Septic System
00-033	0	1071	Warehouse
00-039	0	1071	Underground Storage Tank
01-001(a)	01	1078	Septic System

Module II Page 11 of 16

Table II-3 (Continued)

PRS/SWMU Number	Technical Area	Operational Unit	Unit Type
01-001(b)	01	1078	Septic System
01-001(c)	01	1078	Septic System
01-001(d)	01	1078	Septic System
01-001(e)	01	1078	Septic System
01-001(f)	01	1078	Septic System
01-001(g)	01	1078	Septic System
01-001(h)	01	1078	Septic System
01-001(i)	01	1078	Septic System
01-001(j)	01	1078	Septic System
01-001(k)	01	1078	Septic System
01-001(1)	01	1078	Septic System
01-001(m)	01	1078	Septic System
01-001(n)	01	1078	Septic Tank #276
01-001(o)	01	1078	Ind. or Sm Waste Water Treatment
01-001(s)	01	1078	Septic System
01-001(t)	01	1078	Septic System
01-001(u)	01	1078	Septic System
01-002	45	1079	Outfall TA-01
01-003(a)	01	1078	Landfill
01-003(d)	01	1078	Surface Disposal Site
01-003(e)	01	1078	Surface Disposal Site
01-006(a)	01	1078	Drain, Liner and Outfall
01-006(b)	01	1078	Drain, Liner and Outfall
01-006(c)	01	1078	Drain, Liner and Outfall
01-006(d)	01	1078	Drain, Liner and Outfall

Module II Page 12 of 16

Table II-3 (Continued)

PRS/SWMU Number	Technical Area	Operational Unit	Unit Type
01-006(h)	01	1078	Drain, Liner and Outfall
01-006(n)	01	1078	Drain, Liner and Outfall
01-006(o)	01	1078	Drain, Liner and Outfall
01-007(a)	01	1078	Soil Contamination Area
01-007(b)	01	1078	Soil Contamination Area
01-007(c)	01	1078	Soil Contamination Area
01-007(d)	01	1078	Soil Contamination Area
01-007(e)	01	1078	Soil Contamination Area
01-007(j)	01	1078	Soil Contamination Area
01-007(1)	01	1078	Soil Contamination Area
10-001(a)	10	1079	Firing Site
10-001(b)	10	1079	Firing Site
10-001(c)	10	1079	Firing Site
10-001(d)	10	1079	Firing Site
10-002(a)	10	1079	Disposal Pit
10-002(b)	10	1079	Disposal Pit
10-003(c)	10	1079	Disposal Pit
10-003(d)	10	1079	Disposal Pit
10-003(e)	10	1079	Disposal Pit
10-003(f)	10	1079	Disposal Pit
10-003(g)	10	1079	Manholes
10-003(h)	10	1079	Manholes
10-003(i)	10	1079	Septic Tank
10-003(j)	10	1079	Tank
10-003(k)	10	1079	Tank

Module II Page 13 of 16

Table II-3 (Continued)

PRS/SWMU Number	Technical Area	Operational Unit	Unit Type			
10-003(1)	10	1079	Tank			
10-003(m)	10	1079	Waste Line			
10-003(n)	10	1079	Leach Field			
10-003(o)	10	1079	Leach Field			
10-004(a)	10	1079	Septic System			
10-004(b)	10	1079	Septic System			
10-005	10	1079	Surface Disposal Area			
10-007	10	1079	Landfill			
19-001	19	1071	Septic System			
19-002	19	1071	Septic System			
19-003	19	1071	Septic System			
31-001	31	1079	Septic System			
32-001	32	079	Incinerator			
32-002(a)	32	1079	Septic System			
32-002(b)	32	1079	Septic System			
45-001	45	1079	Waste Water Treatment Facility			
45-002	45	1079	Vehicle Decontamination Area			
45-003	45	1079	Waste Line			
45-004	45	1079	Sanitary Sewer Outfall			
73-001(a)	73	1071	Landfill			
73-001(b)	73	1071	Surface Disposal Area			
73-001(c)	73	1071	Landfill			
73-001(d)	73	1071	Landfill			
73-002	73	1071	Incinerator and Surface Disposal Area			

Module II Page 14 of 16

Table II-3 (Continued)

PRS/SWMU Number	Technical Area	Operational Unit	Unit Type				
73-004(a)	73	1071	Septic System				
73-004(b)	73	1071	Septic System				
73-004(c)	73	1071	Septic System				
73-005	73	1071	Septic System				
73-006	73	1071	Industrial or Sanitary Waste Water Treatment\Facility				

MODULE II TABLE 2-2

List of Off-Site Waste Management Facilities that may return treatment derived waste or waste residuals to Los Alamos National Laboratory.

Off-Site Facility	E.P.A. Identification Number
Argonne National Laboratory, Argonne, IL	IL38900089
Catholic University, Washington, D.C.	DCD980204879
Consolidated Incineration Facility, Savannah River Site, SC	SC1890008989
Diversified Scientific Services, Inc., Kingston, TN	TND982109142
Envirocare, Clive, UT	<u>UTI982598898</u> UTD9825 <u>98898</u>
Waste Experimental Reduction Facility, Idaho National Engineering Laboratory, Idaho Falls, ID	ID4890008952
M4 Environmental Management, Inc., Oak Ridge, TN	RD&D Permit
EG&G Mound Applied Technologies, Miamisburg, OH	ОН6890008984
Nuclear Fuel Services, Erwin, TN	TND003095635
Nuclear Sources & Services, Inc., Houston, TX	TXD982560294
Toxic Substance Control Act Incinerator, Oak Ridge National Laboratory, Oak Ridge, TN	TN0890090004
International Technology Corporation, Technology Center, Knoxville, TN	TND000770479
International Technology Corporation, Biotech Applications Center, Knoxville, TN	TND987782521
International Technology Corporation, Environmental Technology Development Center, Oak Ridge, TN	TND981933120
Perma-Fix, Albuquerque, NM	NM0000182121
Perma-Fix, Gainesville, FL	FLG980711071

MODULE III STORAGE IN CONTAINERS

III.A. DESIGNATED STORAGE UNITS

- 1. <u>Technical Area 54, Area L</u> The Permittee may store for more than ninety days hazardous wastes in containers only in the following designated storage areas:
 - a. Containers containing free liquids may be stored on the concrete containment structure, Facility Number 54-32 and 54-58.
 - b. Containers containing free liquids may be stored in the packaging building, Facility Number 54-31.
 - c. Containers not containing free liquids may be stored, on pallets or otherwise elevated four inches, in a single layer in cleared areas within the fenced portion of Area L, subject to the limitations of HWMR-5, as amended 1989, Part V, 40 CFR Sections 264.175(c) and 264.175(d). Such containers shall not be stored within five feet of the perimeter fence, nor five feet of any structure, nor five feet of the paved or unpaved roadway. Disposal unit covers designed to serve as storage areas are not subject to this exclusion. See Figure 6.
 - d. Gas cylinders will be stored in cylinder racks, or on specially constructed pallets that provide support and restraint, under a self-supporting canopy located in cleared areas within the fenced portion of Area L, within the restrictions of permit paragraph II.G. above.
 - e. The fence line around Area L as shown in permit Figure 6 shall not be altered without prior notice to the Secretary and permit modification in accordance with HWMR-5, as amended 1989, Part IX, 40 CFR Section 270.41 or 270.42 as appropriate.
 - f. Containers containing free liquids may be stored in the modular storage buildings, Model 22 or equivalent, Facility Numbers 54-68 and 54-69, 54-70 for container storage located as shown in Figure 6.
- 2. <u>Technical Area 50</u> The Permittee may store for more than ninety days hazardous wastes in containers only in the following designated storage areas:
 - b. Building 50-37. Containers may be stored within storage room 115, 117, and 118 of the of TA-50-37 as shown in Figure 4.
 - c. Containers containing free liquids may be stored in the modular storage buildings, 0Model 22 or equivalent, Facility Number 50-114.
- 3. <u>Technical Area 50</u> The Permittee may store for more than ninety days hazardous and/or mixed wastes in containers only in the following designated storage areas:

- b. Containers not containing free liquids may be stored on pallets, dollies, or otherwise elevated in Building 50-69, Indoor Container Storage Area (Rooms 102 and 103), and at the Building 50-69 Outdoor Container Storage Area (CSA). Containers containing suspect or known free liquids may be stored on self-containment pallets in Building 50-69, Rooms 102 and 103, and at the Building 50-69 Outdoor CSA. Containers will not be stacked at the Building 50-69, Rooms 102 and 103, storage areas. Containers may be stacked two high at the Building 50-69 Outdoor CSA. See Figure 12.
- 4. <u>Technical Area 54 West</u> The Permittee may store for more than ninety days mixed wastes in containers only in the following designated storage areas.
 - a. Building 54-38 Low Bay CSA. Containers not containing free liquids may be stored on pallets or dollies in the Low Bay CSA. Containers containing suspect or known liquids may be stored on self-containment pallets in the Low Bay CSA. Containers will not be stacked at this storage area. See Figure 13.
 - b. Building 54-38 High Bay CSA. Containers not containing free liquids may be stored on pallets or dollies or otherwise elevated in the High Bay CSA. Containers containing suspect or known liquids may be stored on self-containment pallets in the High Bay CSA. Containers will not be stacked at this storage area. See Figure 13.
 - c. Building 54-38 Loading Dock CSA. Containers may be stored on self-containment pallets in the Loading Dock CSA. Containers will not be stacked at this storage area. See Figure 13.
 - d. Building 54-38 Outdoor CSA. Drums of waste may be stored on self-containment pallets in the Outdoor CSA. Other types of waste containers that are elevated by design may be stored in the Outdoor CSA. Containers will not be stacked at this storage area. See Figure 13.
- 3. <u>Technical Area 54, Area G</u> The Permittee may store for more than ninety days mixed wastes in containers only in the following designated storage areas:
 - a. Mixed waste containers potentially containing free liquids may be stored at TA-54-230 and on Storage Pad 10. Secondary containment will be used for containers with liquid items stored on the asphalt pad. See Figure 11.
 - b. Mixed waste containers not containing free liquids may be stored at TA-54-226, TA-54-229, TA-54-230, TA-54-231, TA-54-232, and on Storage Pad 10. See Figure 11.
 - c. All mixed waste containers stored at TA-54-226, TA-54-229, TA-54-230, TA-54-231, and TA-54-232, and on Storage Pad 10 will be placed on pallets or otherwise elevated four inches. Palletized 55-gallon containers may be stored in groups of four and stacked three high. Palletized overpack containers may be stacked two high. Large containers (80-, 83-, 85-, and 99-gallon drums) will also be stored on pallets but will not be stacked.

Fiberglass-reinforced plywood (FRP) boxes may be stacked two high, at a maximum. Within the modular units at Storage Pad 10, the drums will be elevated above the storage area floor on wheeled drum dollies or steel pallets. For waste stored outdoors on the pad, containers will be protected from storm water run-on/runoff through the use of pallets (or otherwise elevated four inches). Tarpaulins or covers will be used to protect containers and containment pallets from precipitation.

III.B. AUTHORIZED WASTES

- 1. <u>Identification</u> Only hazardous and/or mixed wastes identified in Permit Attachment G. with the process code "S01" in column D.1. "Processes" shall be stored.
- 2. <u>Quantities</u> The cumulative quantity of individual hazardous and/or mixed wastes in storage at any one time at the facility shall not exceed the quantity indicated in Permit Attachment G. Column B. "Estimated Annual Quantity of Waste".
- 3. <u>Land Ban</u> The Permittee must also comply with the following regarding storage of its wastes in containers which are prohibited from land disposal. These restrictions are imposed on any waste as it becomes prohibited from land disposal. (New Mexico Administrative Code, Title 20, Chapter 4, Part 1 (20 NMAC 4.1), Subpart VIII, 268.50, revised November 1, 1995)
 - a. A storage period of one year is permitted. A storage period beyond one year is permitted provided there is proof that such storage is solely for the purpose of accumulation of such quantities as are necessary to facilitate proper recovery, treatment or disposal.
 - b. Each container must be clearly marked as to its contents and the date each period of accumulation begins.
 - c. Hazardous wastes meeting the treatment standards in 20 NMAC 4.1, Subpart VIII, 268.41, 268.42, 268.43, revised November 1, 1995, are not subject to the storage prohibition. Hazardous wastes meeting the treatment standards specified under the variance in 20 NMAC 4.1, Subpart VIII, 268.44, revised November 1, 1995, are not subject to the storage prohibition.

III.C. CONTAINERS

1. Capacity

- a. Lab-packed wastes shall be stored in containers not to exceed 55-gallon nominal capacity.
- b. Bulk liquids may be stored in drums of a nominal capacity of 55-gallons or less.
- c. Solidified hazardous and/or mixed wastes not containing free liquids may be stored in containers meeting U.S. Department of Transportation (DOT) requirements for transportation.

- d. Compressed gases may be stored in any sized cylinder. Small cylinders may be packed in drums or crates complying with DOT shipping regulations.
- e. Polyethylene containers of 220-gallon or 330-gallon capacity may be used in place of 55-gallon drums as long as secondary containment capacity criteria of HWMR-5, as amended 1989, Part V, 40 CFR Section 264.175(b)(3) are not exceeded.
- 2. Type Containers must be of a type specified in the DOT hazardous materials regulations, 49 CFR parts 171 to 179, which specify authorized containers for the waste. As applicable, the containers shall be either: (1) previously unused or reused according to DOT requirements; (2) the original shipping containers in which the material was first marketed; or (3) any other suitable container which satisfies the requirements of permit paragraph III.C. If the hazardous and/or mixed wastes are to be received and stored in their original shipping containers, the Permittee must ensure that the requirements of permit paragraph III.C. are satisfied. Polyethylene bulk containers shall meet or exceed DOT requirements. Compressed gas cylinders not meeting DOT requirements shall be segregated in a safe area.
- 3. Quantity The following quantities include all stored liquid materials, whether regulated or not. Solid materials which do not displace containment capacity may be collocated without affecting these volumes. Solid materials which displace containment volume shall be included in calculating the stored volume as if they were liquids. The Permittee shall keep current accurate records of the quantity of waste in storage at each location below to ensure that these capacities are not exceeded.
 - a. No more than 440 gallons of liquid shall be stored at Technical Area 54, Area L, Building Number 54-31.
 - b. No more than 17,220 gallons of liquid shall be stored at each concrete containment structure: facility Number 54-32.
 - c. No more than 3600 containers of 55-gallon capacity or less, or the equivalent volume of 26,470 cubic feet, 980 cubic yards or 749 cubic meters, shall be used to store solidified wastes at Technical Area 54, Area L.
 - d. No more than 3,630 gallons of liquid shall be stored in Building 50-37, Rooms 115, 117, and 118 combined.
 - e. No more than 1,650 gallons of waste shall be stored in each modular storage unit.
 - h. No more than 1,500 gallons of waste shall be stored at the Building 50-69 Indoor CSA (Rooms 102 and 103). No more than 30,000 gallons of waste shall be stored at the Building 50-69 Outdoor CSA.
 - i. No more than 2,200 gallons of waste shall be stored at the Building 54-38 High Bay CSA. No more than 880 gallons of waste shall be stored at the Building 54-38 Low Bay CSA.

No more than 660 gallons of waste shall be stored at the Building 54-38 Loading Dock CSA. No more than 7,920 gallons of waste shall be stored at the Building 54-38 Outdoor CSA.

g. No more than 970,000 gallons of waste shall be stored at TA-54-226. No more than 790,000 gallons of waste shall be stored at each of the following locations: TA-54-229, TA-54-230, TA-54-231, and TA-54-232. Of the 790,000-gallon total that may be stored in TA-54-230, no more than 93,995 gallons shall be potential liquid-bearing waste. No more than 970,000 gallons of waste shall be stored at TA-54, Area G, Pad 10.

4. Condition

- a. If a container holding hazardous or mixed waste is not in good condition (e.g. severe rusting, structural defects) or if it begins to leak, the Permittee shall transfer the hazardous or mixed waste from such container to a container that is in good condition or otherwise manage the waste in compliance with the conditions of this permit.
- b. The Permittee may use overpack containers of more than 55-gallon capacity to manage defective waste storage containers. Each overpacked container shall be recorded in the facility record.

5. <u>Compatibility of Waste</u> with Containers

- a. The Permittee shall assure, as required by 20 NMAC 4.1, Subpart V, 264.172, revised November 1, 1995, that the ability of the container to contain the waste is not impaired. When necessary, this shall include procedures for determining whether the hazardous or mixed waste is no longer compatible with the shipping container if it is to be stored in its original container (e.g. determination of container adequacy for chemicals that have a finite shelf life or may change in composition upon aging).
- b. The Permittee shall not place into the polyethylene containers described in permit paragraph III.C.1.e. above, any material for which the manufacturer does not rate the container suitability as "Good" or "Excellent" in the current compatibility technical bulletin issued by the manufacturer. A copy of the current bulletin shall be available at the facility.
- 6. <u>Management</u> The Permittee shall manage containers as required by 20 NMAC 4.1, Subpart V, 264.173, revised November 1, 1995, and Permit Attachment F.

III.D. CONTAINMENT

The Permittee shall construct and maintain the containment systems for each storage unit in permit paragraphs III.A. above in accordance with the requirements of 20 NMAC 4.1, Subpart V, 264.175, revised November 1, 1995.

III.E. IGNITABLE OR REACTIVE WASTES

The Permittee shall not locate containers holding ignitable or reactive waste within 15 meters (50 feet) of the facility property line.

III.F. INCOMPATIBLE WASTES

The Permittee shall manage incompatible wastes or incompatible wastes and materials in accordance with the requirements of 20 NMAC 4.1, Subpart V, 264.177, revised November 1, 1995.

III.G. CLOSURE

The Permittee shall comply with the Closure Plan, Permit Attachment E. and permit paragraph II.L. above, for closure of any permitted storage area.

III.H. INSPECTION

- 1. <u>Inspection Plan</u> The Permittee shall inspect the storage areas in accordance with Permit Attachment B.
- 2. <u>Spill Kits</u> The type, presence, location and quantity of spill kits shall be verified and annotated monthly. If spill kits are locked up, the location of access keys shall be verified.
- 3. <u>Warning Signs</u> The legibility and condition of warning signs shall be included in the weekly inspection. Missing or illegible signs shall be promptly replaced within 24 hours of discovery.
 - a. Signs shall be at the entrances to the hazardous and mixed waste units. Collocated units may be included within one signed area.
 - b. Signs shall say "Danger, Unauthorized Personnel Keep Out" and "Hazardous Waste Storage Area".
 - c. Signs shall be in both English and Spanish.
 - d. Signs on approachable perimeter fences shall be spaced no more than 50 feet apart.

CONTAINER MANAGEMENT PERMIT ATTACHMENT F NM0890010515-1

ATTACHMENT F CONTAINER MANAGEMENT

F.1 CONTAINER PACKAGING, SAMPLING and LABELING

F.1.1 Container Packaging and Transport

When chemical substances are declared to be in excess, the originating group completes Waste Profile Form (WPF, see Permit Attachments A.2 and A.3) and sends the form to the Solid Waste Operations Group (FWO-SWO). The WPF provides waste characterization information for subsequent management of material. The WPF is reviewed for adequacy of information and assignation of segregation codes, Department of Transportation information, and Environmental Protection Agency (EPA) Hazardous Waste Numbers. When the WPF is approved, the waste generator submits a Chemical Waste Disposal Request (CWDR) to FWO-SWO. The CWDR lists the chemical waste the generating group needs to dispose of, the quantity of the wastes, and other pertinent information about the containers.

A uniform waste manifest is prepared for use when the waste is collected, packaged, and transported. All waste materials are packaged and transferred in accordance with DOT regulations and the Laboratory's On-Site Transportation Manual.

FWO-SWO personnel review the waste disposal request for adequacy of information and assignation of segregation codes, DOT information, and EPA codes. FWO-SWO personnel then use the waste disposal request to complete the shipping papers for waste collection. Also, FWO-SWO use the waste disposal request to create a second record as part of the Hazardous Waste Database. FWO-SWO personnel visit the generating site to package the waste and transport it to TA-54, Area L. All waste is transferred in accordance with DOT regulations and Laboratory procedures.

Containers will be visually inspected for integrity before transport. If the container is unacceptable, it will be repackaged or overpacked prior to transport. The wastes are transported by vehicles ranging from half-ton to trucks to semitrailers with maximum capacities of up to 80,000 pounds.

Upon arrival at a hazardous or mixed waste management unit, the wastes are unloaded from the transport vehicle and placed into appropriate storage areas. Lab pack waste will be temporary placed at the packaging building for labeling or compositing. Drums and Tuff-Tanks will be placed on either the sampling pad or storage pad for sampling and labeling.

F.1.2 Drum Labeling, Recording, and Sampling System

Each unique package of	waste is labeled with the	ne following information:
------------------------	---------------------------	---------------------------

—chemical segregation group number
—unique record number
—date of generation
—either an EPA hazardous waste label or the words "hazardous waste.

Attachment F Page 1 of 5

- —DOT Hazard class and shipping information, as appropriate
- EPA hazardous waste code(s) or the hazardous constituent(s)

This information and the data from the CWDR are entered into a chemical and mixed waste database. All records are then maintained in accordance with the requirements of this permit.

Sampling of the waste is then performed as outlined in Permit Attachment A. The sampling pad at TA-54, Area L, is restricted to one compatibility group of chemicals at a time (e.g., organics). The group allowed at the time will be posted on the pad. This ensures that incompatible chemicals do not react in the containment basin of the pad. Before a new compatibility group of chemicals is placed on the pad, the containment area will be cleaned. For this reason, the main sampling pad will generally be used for organic waste and acid/base waste will be sampled at the appropriate storage cell.

After all packages are labeled and/or sampled, they are moved to one of the Laboratory's storage areas. The permitted areas are defined in Permit Module III.

F.2 STORAGE AREA PRACTICES

F.2.1 Storage Areas at TA-50 and TA-54

The Laboratory has the following storage areas that are the subject of this permit: modular storage units and the main storage pad at TA-54, Area L; the modular storage unit at TA-50, the storage room; the TA-50-69 indoor and outdoor storage units; and the TA-54-38 storage units; and TA-54-226, -229, -230, -231, -232, and Pad 10 at TA-54, Area G. The usage of each of these units is discussed below.

F.2.1.1 Modular Storage Units, TA-54, Area L (TA-54-68 and -69 and -70)

The primary usage of the modular units will be for the storage of lab pack waste, particularly those in fiberboard containers. After labeling, the lab packs are placed directly in the appropriate storage cell. Each modular unit has two or three cells allowing single chemical family group to be stored in each cell at any one time. However, more than one cell may be used for the same chemical type. Each cell will be labeled as to the chemical family stored there. If at any time the cell designation changes, such as from organic to reactive, the cell will first be cleaned to ensure that no hazardous waste constituent residues remain that would create an incompatibility problem during a spill.

F.2.1.2 Storage Pad at TA-54, Area L (TA-54-32)

Material stored on the storage pad at TA-54, Area L, will generally be placed there after labeling and sampling. This may not be the case for acids and bases where the storage cell is also used as the sampling pad. The pad is divided into six cells allowing the storage of six chemical family groups. However, more than one cell may be used for the same chemical type. All cells will be labeled as to which chemical type is stored there. If at any time it is necessary to change the designation of a cell, it will first be cleaned to remove any residues that might produce an unfavorable reaction with the new chemical type.

F.2.1.3 Modular Storage Unit at TA-50 (TA-50-114)

The modular storage units at TA-50 will be used primarily to store acid and base wastes. Each cell will be labeled acid or base to indicate the type of waste stored there. If at any time the designation of a cell needs to be changed, the cell will first be cleaned to ensure that incompatible residues have been removed.

F.2.1.5 Storage Room at TA-50-37, Room 117

The storage room at TA-50-37 is divided into two areas, one for solids and one for liquids. The liquid side is further divided into two cells. Therefore, up to three chemical types may be stored at any one time. Cells will be labeled as to the chemical type stored there. If at any time the cell designation needs to be changed, the cell will be cleaned to remove any incompatible residues.

F.2.1.6 Storage Pads at TA-54, Area L (TA-54-36 and -58)

The primary activities at TA-54-36 and TA-54-58 will fall into two categories. The first is sorting, surveying, and decontaminating certain waste currently in storage and labeled "suspect mixed waste." All of the waste found to contain no radioactive component will be repackaged, shipped off-site, and disposed of at a permitted Hazardous Waste Treatment, Storage and Disposal Facility.

The second is typically associated with hazardous and mixed waste streams for which commercial treatment and/or disposal is currently available. These waste streams will be staged, inspected, sampled, and analyzed to provide complete hazardous waste and radiological characterization. When these steps are completed, the waste streams will be profiled into the commercial facilities and shipped for ultimate treatment and/or disposal.

The activities at pads #58 and #36 consist of opening the drums, surveying the contents for radiological content, decontaminating the material as warranted, repackaging the material for either return to storage, shipment off-site for disposal, or disposal as low level waste at TA-54, Area G.

Pads #58 and #36 consist of two cement pads that are sloped toward a dry containment sump at the centerline of the rear wall to facilitate pumping of any captured liquids. The walls encircling the pads vary from approximately 4 inches in height at the drive over entrance to the pad to approximately eleven and one-half inches in height at the edge of the dry sump. The "dry sump" in each pad is to provide secondary containment only, has no discharge and must be pumped in the event any liquid is captured. The pads are coated with an impermeable epoxy coating and are covered by a single, metal "pole barn."

Pad #36 has a temporary modular containment structure constructed over it. This structure provides containment and protection for the sampling and repackaging activities. The sides of the structure have been equipped with slanted sheets of plywood to direct the snow and rain away from the secondary containment. The modular containment structure is secured to the beams supporting the "pole barn" wit guy wires. Whenever this temporary structure is removed from Pad #36, it will

be decontaminated according to the procedures of Permit Attachment E.3, E.3.3 and E.3.4: <u>Closure Procedures and Decontamination and Decontamination Verification.</u>

F.2.1.6 TA-54, Area G, Container Storage Areas (TA-54-226, -229, -230, -231, -232, and Pad 10)

The container storage areas (CSA) at TA-54, Area G (TA-54-226, -229, -230, -231, and -232, and Pad 10) will be used for the storage of transuranic (TRU) mixed waste containers retrieved from under earthen cover at Pad 1 (TA-54-226) and Pads 2 and 4. The waste containers, including drums and fiberglass-reinforced plywood (FRP) boxes, will be segregated by LANL waste code prior to being placed in a storage dome. If any of the retrieved containers require overpacking or repackaging, the overpack or repackaging container will be labeled with barcodes that identify the original waste container. In the modular units at Storage Pad 10, waste containers will be stored along the length of the walls of the storage units allowing a center aisle for inspection and passage of emergency equipment. Drums will not be stacked within the modular units. None of the wastes to be placed in the storage domes will be ignitable or reactive, no incompatible wastes will be mixed, and no wastes will be placed in containers that previously held incompatible wastes. TA-54-230 and Storage Pad 10 will be used to store drums and FRP crates that potentially contain liquids. The remaining CSAs will store only solid TRU mixed waste.

F.2.1.7 TA-50-69 Indoor and Outdoor Container Storage Areas

The indoor and outdoor storage areas associated with TA-50-69 are used for storage of TRU mixed waste, low-level mixed waste, and hazardous waste. Potentially incompatible wastes will be segregated on self-containment pallets at both the indoor and outdoor storage areas. Potential liquid-bearing waste containers will be stored on self-containment pallets at both the indoor and outdoor storage areas.

F.2.1.8 TA-54-38 Container Storage Areas

The four container storage areas at TA-54-38 are used for storage of TRU mixed waste and low-level mixed waste. Potentially incompatible wastes will be segregated on self-containment pallets at each storage area. Potential liquid-bearing waste containers will be stored on self-containment pallets at each storage area.

F.2.2 General Container Management Practices

All hazardous recyclable materials are stored as hazardous waste until such time as they are recycled. They are placed in the same segregated storage areas as the other waste.

Any bulging drums are handled in accordance with accepted practice and Laboratory procedures. Generally this means that personnel will follow such practices as slowly venting the drum as it is being opened and personnel wearing protective clothing and splash guards.

Any spills resulting from the transfer/storage of waste will be cleaned up in accordance with Attachment D.

Inspections will be conducted and aisle space will be maintained in accordance with Permit Attachment B.

Off-site shipments of waste will occur at either the given storage area directly or from the transport pad at TA-54, Area L. This will avoid unnecessary transport on Pajarito Road.

Repackaging of waste will generally occur adjacent to the storage area the waste was removed from. Other possible areas include the TA-54, Area L, sampling pad (TA-54-36), and transport pad (TA-54-58); and the TA-50-69 indoor storage area. Repackaging can range from overpacking a leaking container to off-site contractors repackaging the lab pack waste to meet incinerator specifications.

Permit Module III provides additional requirements all container storage areas.

ATTACHMENT G Authorized Wastes NM0890010515-1

				B. Estimated	C. Unit										(2) Process
A.	EPA H	lazardo	ous	Annual	of										Description
	Wast	e No.		Quantity	Measure		(1) Process Codes (enter)						[if a code is not		
	(enter	code)		of Waste	(enter code)			` '			,	,			entered in D(1)]
D	0	0	1	100,000	P	S	0	1							. ,,,
D	0	0	2	320,000	Р	S	0	1	Т	0	1				
D	0	0	3	35,000	Р	S	0	1	Т	0	1				
D	0	0	4	2,000	Р	S	0	1	Т	0	1				
D	0	0	5	60,000	Р	S	0	1	S	0	2	Т	0	1	
D	0	0	6	1,000	Р	S	0	1	Т	0	1				
D	0	0	7	1,500	Р	S	0	1	Т	0	1				
D	0	0	8	100,000	Р	S	0	1	Т	0	1				
D	0	0	9	15,000	Р	S	0	1	Т	0	1				
D	0	1	0	7,500	Р	S	0	1	Т	0	1				
D	0	1	1	7,500	Р	S	0	1	Т	0	1				
D	0	1	2	1,000	Р	S	0	1							
D	0	1	3	500	Р	S	0	1							
D	0	1	4	500	Р	S	0	1							
D	0	1	5	500	Р	S	0	1							
D	0	1	6	1,000	Р	S	0	1							
D	0	1	7	500	Р	S	0	1							
D	0	1	8	15,000	Р	S	0	1							
D	0	1	9	500	Р	S	0	1							
D	0	2	0	500	Р	S	0	1							
D	0	2	1	500	Р	S	0	1							
D	0	2	2	3,000	Р	S	0	1							
D	0	2	3	500	Р	S	0	1							
D	0	2	4	500	Р	S	0	1							
D	0	2	5	500	Р	S	0	1							
D	0	2	6	1,000	Р	S	0	1							
D	0	2	7	500	Р	S	0	1							

NM0890010515-1 G-1

				B. Estimated	C. Unit										(2) Process
A. EPA Hazardous				Annual	of								Description		
	Wast	e No.		Quantity	Measure	(1) Process Codes (enter)								[if a code is not	
	(enter	code)		of Waste	(enter code)									entered in D(1)]	
D	0	2	8	500	Р	S	0	1							
D	0	2	9	500	Р	S	0	1							
D	0	3	0	500	Р	S	0	1							
D	0	3	1	500	Р	S	0	1							
D	0	3	2	500	Р	S	0	1							
D	0	3	3	500	Р	S	0	1							
D	0	3	4	500	Р	S	0	1							
D	0	3	5	2,500	Р	S	0	1							
D	0	3	6	500	Р	S	0	1							
D	0	3	7	500	Р	S	0	1							
D	0	3	8	500	Р	S	0	1							
D	0	3	9	1,000	Р	S	0	1							
D	0	4	0	2,500	Р	S	0	1							
D	0	4	1	500	Р	S	0	1							
D	0	4	2	500	Р	S	0	1							
D	0	4	3	500	Р	S	0	1							
				END OF D DESIGNATOR											

NM0890010515-1 G-2

A. EPA Hazardous Waste No. (enter code)			us	B. Estimated Annual Quantity of Waste	C. Unit of Measure (enter code)	(1) Process Codes (enter)									(2) Process Description [if a code is not entered in D(1)]
F	0	0	1	360,000	Р	S	0	1	S	0	2				Solidified if treatment standards are met
F	0	0	2	75,000	Р	S	0	1	S	0	2				
F	0	0	3	150,000	Р	S	0	1	S	0	2				
F	0	0	4	2,000	Р	S	0	1							
F	0	0	5	100,000	Р	S	0	1	S	0	2				
F	0	0	6	500*	Р	S	0	1	Т	0	1				
F	0	0	7	12,500	Р	s	0	1	Т	0	1				
F	0	0	8	1,000	Р	S	0	1	Т	0	1				
F	0	0	9	6,000	Р	S	0	1	Т	0	1				
F	0	2	7	700	Р	S	0	1							
F	0	2	8	700	Р	S	0	1							
				END OF F DESIGNATOR											

NM0890010515-1 G-3

A.		lazardo e No.	ous	B. Estimated Annual Quantity of Waste	C. Unit of Measure (enter code)			(1) Proce	ss Cod	des (en	ter)		(2) Process Description [if a code is not entered in D(1)]
K	0	4	4	20,000	Р	S	0	1						
K	0	4	7	500*	Р	S	0	1						
К	0	4	5	2,000	Р	S	0	1						
				END OF K DESIGNATOR										

				B. Estimated	C. Unit									(2) Process
A.	EPA H	lazardo	ous	Annual	of									Description
	Wast	te No.		Quantity	Measure			(1) Proce	ss Coo	des (en	iter)		[if a code is not
	(enter	code)		of Waste	(enter code)									entered in D(1)]
Р	0	0	1	1,000	Р	S	0	1						
Р	0	0	2	1,000	Р	S	0	1						
Р	0	0	3	1,000	Р	S	0	1						
Р	0	0	4	1,000	Р	S	0	1						
Р	0	0	5	1,000	Р	S	0	1						
Р	0	0	6	1,000	Р	S	0	1						
Р	0	0	7	1,000	Р	S	0	1						
Р	0	0	8	1,000	Р	S	0	1						
Р	0	0	9	1,000	Р	S	0	1						
Р	0	1	0	1,000	Р	S	0	1						
Р	0	1	1	1,000	Р	S	0	1						
Р	0	1	2	1,000	Р	S	0	1						
Р	0	1	3	1,000	Р	S	0	1	Т	0	1			
Р	0	1	4	1,000	Р	S	0	1						
Р	0	1	5	1,000	Р	S	0	1						
Р	0	1	6	1,000	Р	S	0	1						
Р	0	1	7	1,000	Р	S	0	1						
Р	0	1	8	1,000	Р	S	0	1						
Р	0	2	0	1,000	Р	S	0	1						
Р	0	2	1	1,000	Р	S	0	1	Т	0	1			
Р	0	2	2	1,000	Р	S	0	1						
Р	0	2	3	1,000	Р	S	0	1						
Р	0	2	4	1,000	Р	S	0	1						
Р	0	2	6	1,000	Р	S	0	1						
Р	0	2	7	1,000	Р	S	0	1						
Р	0	2	8	1,000	Р	S	0	1						
Р	0	2	9	500*	Р	S	0	1	Т	0	1			
Р	0	3	0	500*	Р	S	0	1	Т	0	1			
Р	0	3	1	500*	Р	S	0	1						
Р	0	3	3	500*	Р	S	0	1						
Р	0	3	4	500*	Р	S	0	1						
													-	

				B. Estimated	C. Unit									(2) Process
A.	EPA H	lazardo	ous	Annual	of									Description
	Wast	e No.		Quantity	Measure			(1) Proce	ss Cod	des (er	iter)		[if a code is not
	(enter	code)		of Waste	(enter code)									entered in D(1)]
Р	0	3	6	500*	Р	S	0	1						
Р	0	3	7	500*	Р	S	0	1						
Р	0	3	8	500*	Р	S	0	1						
Р	0	3	9	500*	Р	S	0	1						
Р	0	4	0	500*	Р	S	0	1						
Р	0	4	1	500*	Р	S	0	1						
Р	0	4	2	500*	Р	S	0	1						
Р	0	4	3	500*	Р	S	0	1						
Р	0	4	4	500*	Р	S	0	1						
Р	0	4	5	500*	Р	S	0	1						
Р	0	4	6	500*	Р	S	0	1						
Р	0	4	7	500*	Р	S	0	1						
Р	0	4	8	500*	Р	S	0	1						
Р	0	4	9	500*	Р	S	0	1						
Р	0	5	0	500*	Р	S	0	1						
Р	0	5	1	500*	Р	S	0	1						
Р	0	5	4	500*	Р	S	0	1	Т	0	1			
Р	0	5	6	6,000	Р	S	0	1						
Р	0	5	7	500*	Р	S	0	1						
Р	0	5	8	500*	Р	S	0	1						
Р	0	5	9	500*	Р	S	0	1						
Р	0	6	0	500*	Р	S	0	1						
Р	0	6	2	500*	Р	S	0	1						
Р	0	6	3	500*	Р	S	0	1						
Р	0	6	4	500*	Р	S	0	1						
Р	0	6	5	500*	Р	S	0	1						
Р	0	6	6	500*	Р	S	0	1						
Р	0	6	7	500*	Р	S	0	1						
Р	0	6	8	500*	Р	S	0	1						
Р	0	6	9	500*	Р	S	0	1						
Р	0	7	0	500*	Р	S	0	1						

Α.	EPA H		ous	B. Estimated Annual	C. Unit of						(2) Process Description			
	Wast			Quantity	Measure			(1)	Proce	ss Coo	les (en	iter)		[if a code is not
		code)		of Waste	(enter code)						1		I	entered in D(1)]
Р	0	7	1	500*	Р	S	0	1						
Р	0	7	2	500*	Р	S	0	1						
Р	0	7	3	500*	Р	S	0	1	Т	0	1			
Р	0	7	4	500*	Р	S	0	1	Т	0	1			
Р	0	7	5	500*	Р	S	0	1						
Р	0	7	6	500*	Р	S	0	1	Т	0	1			
Р	0	7	7	500*	Р	S	0	1						
Р	0	7	8	500*	Р	S	0	1	Т	0	1			
Р	0	8	1	500*	Р	S	0	1						
Р	0	8	2	500*	Р	S	0	1						
Р	0	8	4	500*	Р	S	0	1						
Р	0	8	5	500*	Р	S	0	1						
Р	0	8	7	500*	Р	S	0	1						
Р	0	8	8	500*	Р	S	0	1						
Р	0	8	9	500*	Р	S	0	1						
Р	0	9	2	500*	Р	S	0	1						
Р	0	9	3	500*	Р	S	0	1						
Р	0	9	4	500*	Р	S	0	1						
Р	0	9	5	500*	Р	S	0	1						
Р	0	9	6	500*	Р	S	0	1						
Р	0	9	7	500*	Р	S	0	1						
Р	0	9	8	500*	Р	S	0	1	Т	0	1			
Р	0	9	9	500*	Р	S	0	1	Т	0	1			
Р	1	0	1	500*	Р	S	0	1						
Р	1	0	2	500*	Р	S	0	1						
Р	1	0	3	500*	Р	S	0	1						
Р	1	0	4	500*	Р	S	0	1	Т	0	1		1	
Р	1	0	5	500*	Р	S	0	1						
Р	1	0	6	500*	Р	S	0	1	Т	0	1			
Р	1	0	8	500*	Р	S	0	1					1	
Р	1	0	9	500*	Р	S	0	1						

				B. Estimated	C. Unit										(2) Process
A.	EPA H	lazardo	ous	Annual	of										Description
	Wast	e No.		Quantity	Measure			(1)) Proce	ss Coo	des (en	ter)			[if a code is not
	(enter	code)		of Waste	(enter code)										entered in D(1)]
Р	1	1	0	500*	Р	S	0	1							
Р	1	1	1	500*	Р	S	0	1							
Р	1	1	2	500*	Р	S	0	1							
Р	1	1	3	500*	Р	S	0	1	Т	0	1				
Р	1	1	4	500*	Р	S	0	1	Т	0	1				
Р	1	1	5	500*	Р	S	0	1	Т	0	1				
Р	1	1	6	500*	Р	S	0	1							
Р	1	1	8	500*	Р	S	0	1							
Р	1	1	9	500*	Р	S	0	1							
Р	1	2	0	500*	Р	S	0	1							
Р	1	2	1	1,000	Р	S	0	1	Т	0	1				
Р	1	2	2	1,000	Р	S 0 1 1 0 1									
Р	1	2	3	1,000	Р	S	0	1							
				END OF P											
				DESIGNATOR											
-															

				B. Estimated	C. Unit									(2) Process
A.	EPA H	lazardo	ous	Annual	of									Description
	Wast	e No.		Quantity	Measure			(1)) Proce	ss Coo	les (en	iter)		[if a code is not
	(enter	code)		of Waste	(enter code)									entered in D(1)]
U	0	0	1	500*	Р	S	0	1						
U	0	0	2	1,000	Р	S	0	1						
U	0	0	3	500*	Р	S	0	1						
U	0	0	4	500*	Р	S	0	1						
U	0	0	5	500*	Р	S	0	1						
U	0	0	6	500*	Р	S	0	1						
U	0	0	7	500*	Р	S	0	1						
U	0	0	8	500*	Р	S	0	1						
U	0	0	9	500*	Р	S	0	1						
U	0	1	0	500*	Р	S	0	1						
U	0	1	1	500*	Р	S	0	1						
U	0	1	2	500*	Р	S	0	1						
U	0	1	4	500*	Р	S	0	1						
U	0	1	5	500*	Р	S	0	1						
U	0	1	6	500*	Р	S	0	1						
U	0	1	7	500*	Р	S	0	1						
U	0	1	8	500*	Р	S	0	1						
U	0	1	9	1,000	Р	S	0	1						
U	0	2	0	500*	Р	S	0	1						
U	0	2	1	500*	Р	S	0	1						
U	0	2	2	500*	Р	S	0	1						
U	0	2	3	500*	Р	S	0	1						
U	0	2	4	500*	Р	S	0	1						
U	0	2	5	500*	Р	S	0	1						
U	0	2	6	500*	Р	S	0	1						
U	0	2	7	500*	Р	S	0	1						
U	0	2	8	1,000	Р	S	0	1						
U	0	2	9	1,000	Р	S	0	1						
U	0	3	0	1,000	Р	S	0	1						
U	0	3	1	1,000	Р	S	0	1						
U	0	3	2	1,000	Р	S	0	1	Т	0	1			
U	0	3	3	1,000	Р	S	0	1						

				B. Estimated	C. Unit									(2) Process
A.	EPA H	lazardo	ous	Annual	of									Description
	Wast	e No.		Quantity	Measure			(1)) Proce	ss Cod	des (en	iter)		[if a code is not
	(enter	code)		of Waste	(enter code)									entered in D(1)]
U	0	3	4	1,000	Р	S	0	1						
U	0	3	5	1,000	Р	S	0	1						
U	0	3	6	1,000	Р	S	0	1						
U	0	3	7	1,000	Р	S	0	1						
U	0	3	8	1,000	Р	S	0	1						
U	0	3	9	1,000	Р	S	0	1						
U	0	4	1	1,000	Р	S	0	1						
U	0	4	2	1,000	Р	S	0	1						
U	0	4	3	1,000	Р	S	0	1						
U	0	4	4	1,000	Р	S	0	1						
U	0	4	5	1,000	Р	S	0	1						
U	0	4	6	1,000	Р	S	0	1						
U	0	4	7	1,000	Р	S	0	1						
U	0	4	8	1,000	Р	S	0	1						
U	0	4	9	1,000	Р	S	0	1						
U	0	5	0	1,000	Р	S	0	1						
U	0	5	1	1,000	Р	S	0	1						
U	0	5	2	1,000	Р	S	0	1						
U	0	5	3	1,000	Р	S	0	1						
U	0	5	5	1,000	Р	S	0	1						
U	0	5	6	500*	Р	S	0	1						
U	0	5	7	500*	Р	S	0	1						
U	0	5	8	500*	Р	S	0	1						
U	0	5	9	500*	Р	S	0	1						
U	0	6	0	500*	Р	S	0	1						
U	0	6	1	500*	Р	S	0	1						
U	0	6	2	500*	Р	S	0	1						
U	0	6	3	500*	Р	S	0	1						
U	0	6	4	500*	Р	S	0	1						
U	0	6	6	500*	Р	S	0	1						
U	0	6	7	500*	Р	S	0	1						
U	0	6	8	500*	Р	S	0	1						

				B. Estimated	C. Unit									(2) Process
A.	EPA H	lazardo	ous	Annual	of									Description
	Wast	e No.		Quantity	Measure			(1)) Proce	ss Cod	des (en	iter)		[if a code is not
	(enter	code)		of Waste	(enter code)									entered in D(1)]
U	0	6	9	500*	Р	S	0	1						
U	0	7	0	500*	Р	S	0	1						
U	0	7	1	500*	Р	S	0	1						
U	0	7	2	500*	Р	S	0	1						
U	0	7	3	500*	Р	S	0	1						
U	0	7	4	500*	Р	S	0	1						
U	0	7	5	500*	Р	S	0	1						
U	0	7	6	500*	Р	S	0	1						
U	0	7	7	500*	Р	S	0	1						
U	0	7	8	500*	Р	S	0	1						
U	0	7	9	500*	Р	S	0	1						
U	0	8	0	1,000	Р	S	0	1						
U	0	8	1	500*	Р	S	0	1						
U	0	8	2	500*	Р	S	0	1						
U	0	8	3	500*	Р	S	0	1						
U	0	8	4	500*	Р	S	0	1						
U	0	8	5	500*	Р	S	0	1						
U	0	8	6	500*	Р	S	0	1						
U	0	8	7	500*	Р	S	0	1						
U	0	8	8	500*	Р	S	0	1						
U	0	8	9	500*	Р	S	0	1						
U	0	9	0	500*	Р	S	0	1						
U	0	9	1	500*	Р	S	0	1						
U	0	9	2	500*	Р	S	0	1						
U	0	9	3	500*	Р	S	0	1						
U	0	9	4	500*	Р	S	0	1						
U	0	9	5	500*	Р	S	0	1						
U	0	9	6	500*	Р	S	0	1						
U	0	9	7	500*	Р	S	0	1						
U	0	9	8	500*	Р	S	0	1						
U	0	9	9	500*	Р	S	0	1						
U	1	0	1	500*	Р	S	0	1						

				B. Estimated	C. Unit									(2) Process
A.	EPA H	lazardo	us	Annual	of									Description
	Wast	te No.		Quantity	Measure			(1)) Proce	ss Coo	les (en	ter)		[if a code is not
	(enter	code)		of Waste	(enter code)									entered in D(1)]
U	1	0	2	500*	Р	S	0	1						
U	1	0	3	500*	Р	S	0	1						
U	1	0	5	500*	Р	S	0	1						
U	1	0	6	500*	Р	S	0	1						
U	1	0	7	500*	Р	S	0	1						
U	1	0	8	500*	Р	S	0	1						
U	1	0	9	500*	Р	S	0	1						
U	1	1	0	500*	Р	S	0	1						
U	1	1	1	500*	Р	S	0	1						
U	1	1	2	500*	Р	S	0	1						
U	1	1	3	500*	Р	S	0	1						
U	1	1	4	500*	Р	S	0	1						
U	1	1	5	500*	Р	S	0	1						
U	1	1	6	500*	Р	S	0	1						
U	1	1	7	500*	Р	S	0	1						
U	1	1	8	500*	Р	S	0	1						
U	1	1	9	500	Р	S	0	1						
U	1	2	0	500*	Р	S	0	1						
U	1	2	1	500*	Р	S	0	1						
U	1	2	2	1,000	Р	S	0	1						
U	1	2	3	500*	Р	S	0	1						
U	1	2	4	500*	Р	S	0	1						
U	1	2	5	500*	Р	S	0	1						
U	1	2	6	500*	Р	S	0	1						
U	1	2	7	500*	Р	S	0	1						
U	1	2	8	500*	Р	S	0	1						
U	1	2	9	500*	Р	S	0	1						
U	1	3	0	500*	Р	S	0	1						
U	1	3	1	500*	Р	S	0	1						
U	1	3	2	500*	Р	S	0	1						
U	1	3	3	500*	Р	S	0	1						
U	1	3	4	10,000	Р	S	0	1	Т	0	1			

				B. Estimated	C. Unit										(2) Process
A.	EPA H	lazardo	ous	Annual	of										Description
	Wast	te No.		Quantity	Measure			(1)	Proce	ss Coo	des (en	ter)			[if a code is not
	(enter	code)		of Waste	(enter code)										entered in D(1)]
U	1	3	5	500*	Р	S	0	1				Т	0	1	
U	1	3	6	500*	Р	S	0	1							
U	1	3	7	1,000	Р	S	0	1							
U	1	3	8	1,000	Р	S	0	1							
U	1	4	0	1,000	Р	S	0	1							
U	1	4	1	1,000	Р	S	0	1							
U	1	4	2	1,000	Р	S	0	1							
U	1	4	3	1,000	Р	S	0	1							
U	1	4	4	1,000	Р	S	0	1							
U	1	4	5	1,000	Р	S	0	1							
U	1	4	6	1,000	Р	S	0	1							
U	1	4	7	1,000	Р	S	0	1							
U	1	4	8	1,000	Р	S	0	1							
U	1	4	9	1,000	Р	S	0	1							
U	1	5	0	1,000	Р	S	0	1							
U	1	5	1	1,000	Р	S	0	1							
U	1	5	2	1,000	Р	S	0	1							
U	1	5	3	1,000	Р	S	0	1							
U	1	5	4	1,000	Р	S	0	1							
U	1	5	5	1,000	Р	S	0	1							
U	1	5	6	1,000	Р	S	0	1							
U	1	5	7	1,000	Р	S	0	1							
U	1	5	8	1,000	Р	S	0	1							
U	1	5	9	1,000	Р	S	0	1							
U	1	6	0	1,000	Р	S	0	1							
U	1	6	1	1,000	Р	S	0	1							
U	1	6	2	1,000	Р	S	0	1							
U	1	6	3	500*	Р	S	0	1							
U	1	6	4	500*	Р	S	0	1							
U	1	6	5	500*	Р	S	0	1							
U	1	6	6	500*	Р	S	0	1							

				B. Estimated	C. Unit									(2) Process
A.	EPA H	lazardo	ous	Annual	of									Description
	Wast	e No.		Quantity	Measure			(1)) Proce	ss Cod	des (en	iter)		[if a code is not
	(enter	code)		of Waste	(enter code)									entered in D(1)]
U	1	6	7	500*	Р	S	0	1						
U	1	6	8	500*	Р	S	0	1						
U	1	6	9	500*	Р	S	0	1						
U	1	7	0	500*	Р	S	0	1						
U	1	7	1	500*	Р	S	0	1						
U	1	7	2	500*	Р	S	0	1						
U	1	7	3	500*	Р	S	0	1						
U	1	7	4	500*	Р	S	0	1						
U	1	7	6	500*	Р	S	0	1						
U	1	7	7	500*	Р	S	0	1						
U	1	7	8	500*	Р	S	0	1						
U	1	7	9	500*	Р	S	0	1						
U	1	8	0	500*	Р	S	0	1						
U	1	8	1	500*	Р	S	0	1						
U	1	8	2	500*	Р	S	0	1						
U	1	8	3	500*	Р	S	0	1						
U	1	8	4	500*	Р	S	0	1						
U	1	8	5	500*	Р	S	0	1						
U	1	8	6	500*	Р	S	0	1						
U	1	8	7	500*	Р	S	0	1						
U	1	8	8	1,000	Р	S	0	1						
U	1	8	9	500*	Р	S	0	1						
U	1	9	0	500*	Р	S	0	1						
U	1	9	1	500*	Р	S	0	1						
U	1	9	2	500*	Р	S	0	1						
U	1	9	3	500*	Р	S	0	1						
U	1	9	4	500*	Р	S	0	1						
U	1	9	6	500*	Р	S	0	1						
U	1	9	7	500*	Р	S	0	1						
U	2	0	0	500*	Р	S	0	1						
U	2	0	1	500*	Р	S	0	1						
U	2	0	2	500*	Р	S	0	1						

				B. Estimated	C. Unit									(2) Process
A.	EPA H	lazardo	ous	Annual	of									Description
	Wast	te No.		Quantity	Measure			(1	Proce	ss Coo	les (en	ter)		[if a code is not
	(enter	code)		of Waste	(enter code)									entered in D(1)]
U	2	0	3	500*	Р	S	0	1						
U	2	0	4	500*	Р	S	0	1						
U	2	0	5	500*	Р	S	0	1						
U	2	0	6	500*	Р	S	0	1						
U	2	0	7	500*	Р	S	0	1						
U	2	0	8	500*	Р	S	0	1						
U	2	0	9	500*	Р	S	0	1						
U	2	1	0	500*	Р	S	0	1						
U	2	1	1	1,000	Р	S	0	1						
U	2	1	3	500*	Р	S	0	1						
U	2	1	4	500*	Р	S	0	1						
U	2	1	5	500*	Р	S	0	1						
U	2	1	6	500*	Р	S	0	1						
U	2	1	7	500*	Р	S	0	1						
U	2	1	8	500*	Р	S	0	1						
U	2	1	9	500*	Р	S	0	1						
U	2	2	0	1,000	Р	S	0	1						
U	2	2	1	500*	Р	S	0	1						
U	2	2	2	500*	Р	S	0	1						
U	2	2	3	1,000	Р	S	0	1						
U	2	2	5	500*	Р	S	0	1						
U	2	2	6	1,500	Р	S	0	1						
U	2	2	7	500*	Р	S	0	1						
U	2	2	8	2,000	Р	S	0	1						
U	2	3	4	500*	Р	S	0	1						
U	2	3	5	500*	Р	S	0	1						
U	2	3	6	500*	Р	S	0	1						

A.		lazardo e No. code)	ous	B. Estimated Annual Quantity of Waste	C. Unit of Measure (enter code)	(1) Process Codes (enter)					(2) Process Description [if a code is not entered in D(1)]		
U	2	3	7	500*	Р	S	0	1					
U	2	3	8	500*	Р	S	0	1					
U	2	3	9	1,000	Р	S	0	1					
U	2	4	0	500*	Р	S	0	1					
U	2	4	3	500*	Р	S	0	1					
U	2	4	4	500*	Р	S	0	1					
U	2	4	6	500*	Р	S	0	1					
U	2	4	7	500*	Р	S	0	1					
U	2	4	8	500*	Р	S	0	1					
U	2	4	9	500*	Р	S	0	1					
U	3	5	3	500*	Р	S	0	1					
U	3	5	9	500*	Р	S	0	1					
				END OF U DESIGNATOR									

EPA I.D. I	Number (Enter from		Secon	dary	ID N	Num	ber (Έ	nter	fro	m	Pag	je 1)	
	NM0890010515													
	ΧI\	/. Description of	Hazardous W	astes (C	ontir	nued)							
							D.	PROCI	ES	SES				
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)	(1) PROCESS CODES (2) PROCESS DESCRIPTIO code is not entered in D						•				
	Technica	l Area 50, Building 69	, Indoor and Outd	loor Conta	iner S	torag	e Area	1						
263	D001	1,170	К	S01						ransu		: Mi	xed V	LMW) Vaste
264	D002	610	К	S01					L	LMW	and	TR	UMW	į.
265	D003	60	К	S01					L	LMW	and	TR	UMW	
266	D004	390	К	S01					L	LMW	and	TR	UMW	
267	D005	360	К	S01					L	LMW	and	TR	UMW	
268	D006	57,130	К	S01					L	LMW	and	TR	UMW	
269	D007	59,610	К	S01					L	LMW	and	TR	UMW	
270	D008	135,280	K	S01					L	LMW	and	TR	UMW	
271	D009	4,120	К	S01					L	LMW	and	TR	UMW	
272	D010	430	К	S01					L	LMW	and	TR	UMW	
273	D011	480	К	S01					L	LMW	and	TR	UMW	
274	D018	20	К	S01					L	LMW	and	TR	UMW	
275	D019	450	К	S01					L	LMW	and	TR	UMW	
276	D021	170	К	S01					L	LMW	and	TR	UMW	
277	D022	100	К	S01					L	LMW	and	TR	UMW	
278	D027	70	К	S01					L	LMW	and	TR	UMW	
279	D028	18,250	K	S01					L	LMW	and	TR	UMW	
280	D029	18,160	K	S01					L	LMW	and	TR	UMW	
281	D030	410	K	S01 LLMW and TRUMW										
282	D031	10	K	S01 LLMW and TRUMW										
283	D032	260	K	S01 LLMW and TRUMW										
284	D033	180	K	S01 LLMW and TRUMW										
285	D034	90	K	S01					L	LMW	and	TR	UMW	

EPA I.D. N	Number <i>(Enter from</i>	Page 1)	Secondary ID Number (Enter from Page 1)							
	NM0890010515									
	ΧIV	/. Description of	Hazardous W	astes (Cor	ntinued)					
	A. EPA Hazardous			D. PROCESSES						
Line Number	Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)	` ´	(1) PROCESS CODES (enter) (2) PROCESS DESC code is not entered					
286	D035	10	K	S01		LLMW and TRUMW				
287	D036	30	K	S01		LLMW and TRUMW				
288	D037	50	K	S01		LLMW and TRUMW				
289	D038	10	K	S01		LLMW and TRUMW				
290	D039	120	K	S01		LLMW and TRUMW				
291	D040	280	K	S01		LLMW and TRUMW				
292	D041	10	K	S01		LLMW and TRUMW				
293	D042	90	K	S01		LLMW and TRUMW				
294	D043	40	K	S01		LLMW and TRUMW				
295	F001	35,050	K	S01		LLMW and TRUMW				
296	F002	4,540	K	S01		LLMW and TRUMW				
297	F003	2,300	K	S01		LLMW and TRUMW				
298	F004	130	К	S01		LLMW and TRUMW				
299	F005	20,430	К	S01		LLMW and TRUMW				
300	P003	10	K	S01		LLMW and TRUMW				
301	P012	10	K	S01		LLMW and TRUMW				
302	P015	10	K	S01		LLMW and TRUMW				
303	P029	10	K	S01		LLMW and TRUMW				
304	P030	10	K	S01		LLMW and TRUMW				
305	P031	10	K	S01		LLMW and TRUMW				
306	P038	10	K	S01		LLMW and TRUMW				
307	P056	20	K	S01		LLMW and TRUMW				
308	P063	10	K	S01		LLMW and TRUMW				
309	P068	10	K	S01		LLMW and TRUMW				
310	P073	110	K	S01		LLMW and TRUMW				
311	P076	10	K	S01		LLMW and TRUMW				
312	P078	10	K	S01		LLMW and TRUMW				

EPA I.D. N	Number <i>(Enter from</i>	Page 1)		Secondary ID Number (Enter from Page 1)						
	NM0890010515									
	ΧI\	/. Description of	Hazardous W	astes (Con	ntinued)					
	4 FD4 //			D. PROCESSES						
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)	, ,	(1) PROCESS CODES (2) PROCESS DESC code is not entered					
313	P095	10	K	S01		LLMW and TRUMW				
314	P096	10	K	S01		LLMW and TRUMW				
315	P098	10	K	S01		LLMW and TRUMW				
316	P106	10	K	S01		LLMW and TRUMW				
317	P113	10	K	S01		LLMW and TRUMW				
318	P120	10	K	S01		LLMW and TRUMW				
319	U001	10	K	S01		LLMW and TRUMW				
320	U002	10	K	S01		LLMW and TRUMW				
321	U003	10	K	S01		LLMW and TRUMW				
322	U012	10	K	S01		LLMW and TRUMW				
323	U019	10	K	S01		LLMW and TRUMW				
324	U022	10	K	S01		LLMW and TRUMW				
325	U029	10	K	S01		LLMW and TRUMW				
326	U031	10	K	S01		LLMW and TRUMW				
327	U037	10	K	S01		LLMW and TRUMW				
328	U044	10	K	S01		LLMW and TRUMW				
329	U045	10	K	S01		LLMW and TRUMW				
330	U052	10	K	S01		LLMW and TRUMW				
331	U056	10	K	S01		LLMW and TRUMW				
332	U057	10	K	S01		LLMW and TRUMW				
333	U075	10	K	S01		LLMW and TRUMW				
334	U077	10	K	S01		LLMW and TRUMW				
335	U080	10	K	S01		LLMW and TRUMW				
336	U108	10	K	S01		LLMW and TRUMW				
337	U112	10	K	S01		LLMW and TRUMW				
338	U115	10	K	S01		LLMW and TRUMW				
339	U117	10	K	S01		LLMW and TRUMW				

EPA I.D. N	Number <i>(Enter from</i>	Page 1)	Secondary ID Number (Enter from Page 1)						
	NM0890010515								
	ΧI\	/. Description of	Hazardous W	astes (Con	tinued)				
	A EDA Hamardana				D.	PROCESSES			
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)	, ,	(2) PROCESS CODES (2) PROCESS DESCRIPTION (enter)				
340	U121	10	K	S01		LLMW and TRUMW			
341	U122	10	K	S01		LLMW and TRUMW			
342	U123	10	K	S01		LLMW and TRUMW			
343	U131	10	K	S01		LLMW and TRUMW			
344	U133	10	K	S01		LLMW and TRUMW			
345	U134	10	K	S01		LLMW and TRUMW			
346	U135	10	K	S01		LLMW and TRUMW			
347	U140	10	K	S01		LLMW and TRUMW			
348	U144	10	K	S01		LLMW and TRUMW			
349	U145	10	K	S01		LLMW and TRUMW			
350	U151	10	K	S01		LLMW and TRUMW			
351	U154	10	K	S01		LLMW and TRUMW			
352	U159	10	К	S01		LLMW and TRUMW			
353	U160	10	K	S01		LLMW and TRUMW			
354	U161	10	К	S01		LLMW and TRUMW			
355	U165	10	K	S01		LLMW and TRUMW			
356	U169	10	К	S01		LLMW and TRUMW			
357	U188	10	K	S01		LLMW and TRUMW			
358	U190	10	K	S01		LLMW and TRUMW			
359	U196	10	K	S01		LLMW and TRUMW			
360	U204	10	K	S01		LLMW and TRUMW			
361	U210	10	K	S01		LLMW and TRUMW			
362	U211	10	K	S01		LLMW and TRUMW			
363	U213	10	K	S01		LLMW and TRUMW			
364	U216	10	K	S01		LLMW and TRUMW			
365	U218	10	K	S01		LLMW and TRUMW			
366	U219	10	K	S01		LLMW and TRUMW			

EPA I.D. N	Number <i>(Enter from</i>	Page 1)	Secondary ID Number (Enter from Page 1)						
	NM0890010515								
	ΧI\	/. Description of	Hazardous W	astes (Co	ntinued)				
					D.	PROCESSES			
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)	, ,	(1) PROCESS CODES (2) PROCESS DES code is not ente				
367	U220	10	K	S01		LLMW and TRUMW			
368	U225	10	K	S01		LLMW and TRUMW			
369	U226	10	K	S01		LLMW and TRUMW			
370	U227	10	K	S01		LLMW and TRUMW			
371	U228	10	K	S01		LLMW and TRUMW			
372	U239	10	K	S01		LLMW and TRUMW			
373	U246	10	К	S01		LLMW and TRUMW			
374	D001	25,360	K	S01		Hazardous Waste (HW)			
375	D002	20,550	K	S01		HW			
376	D003	1,200	K	S01		HW			
377	D004	1,700	K	S01		HW			
378	D005	1,900	K	S01		HW			
379	D006	5,250	K	S01		HW			
380	D007	9,400	K	S01		HW			
381	D008	39,200	K	S01		HW			
382	D009	16,400	K	S01		HW			
383	D010	2,150	K	S01		HW			
384	D011	11,700	K	S01		HW			
385	D016	10	K	S01		HW			
386	D017	20	K	S01		HW			
387	D018	2,270	K	S01		HW			
388	D019	40	K	S01		HW			
389	D021	110	K	S01		HW			
390	D022	1,450	K	S01		HW			
391	D026	180	K	S01		HW			
392	D027	80	K	S01		HW			
393	D028	18,400	K	S01		HW			

EPA I.D. N	Number <i>(Enter from</i>	Page 1)		Secondary ID Number (Enter from Page 1)					
	NM0890010515								
	ΧI\	/. Description of	Hazardous W	astes (Co	ontinued)				
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)		CESS CODES enter)	(2) PROCESS DESCRIPTION (If a code is not entered in D(1))			
394	D029	18,300	K	S01		HW			
395	D030	730	K	S01		HW			
396	D031	10	K	S01		HW			
397	D032	300	K	S01		HW			
398	D033	210	K	S01		HW			
399	D034	120	K	S01		HW			
400	D035	670	K	S01		HW			
401	D036	50	K	S01		HW			
402	D037	50	K	S01		HW			
403	D038	580	K	S01		HW			
404	D039	200	K	S01		HW			
405	D040	570	K	S01		HW			
406	D041	10	К	S01		HW			
407	D042	100	K	S01		HW			
408	D043	60	K	S01		HW			
409	F001	51,170	K	S01		HW			
410	F002	46,030	K	S01		HW			
411	F003	12,770	K	S01		HW			
412	F004	660	K	S01		HW			
413	F005	61,650	K	S01		HW			
414	F009	20	K	S01		HW			
415	F027	20	K	S01		HW			
416	P003	10	K	S01		HW			
417	P006	10	K	S01		HW			
418	P011	10	K	S01		HW			
419	P012	10	K	S01		HW			
420	P015	10	K	S01		HW			

EPA I.D. N	Number <i>(Enter from</i>	Page 1)		Secondary ID Number (Enter from Page 1)					
	NM0890010515								
	ΧI\	/. Description of	Hazardous W	astes (Co	ontinued)				
					D.	PROCESSES			
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)		CESS CODES enter)	(2) PROCESS DESCRIPTION (If a code is not entered in D(1))			
421	P029	10	K	S01		HW			
422	P030	10	K	S01		HW			
423	P031	10	K	S01		HW			
424	P033	10	K	S01		HW			
425	P038	10	K	S01		HW			
426	P043	10	K	S01		HW			
427	P048	10	K	S01		HW			
428	P056	1,030	К	S01		HW			
429	P063	10	K	S01		HW			
430	P068	10	K	S01		HW			
431	P073	10	К	S01		HW			
432	P076	60	K	S01		HW			
433	P078	70	K	S01		HW			
434	P092	10	K	S01		HW			
435	P095	10	K	S01		HW			
436	P096	10	K	S01		HW			
437	P098	10	K	S01		HW			
438	P104	10	K	S01		HW			
439	P105	10	K	S01		HW			
440	P106	10	K	S01		HW			
441	P112	10	K	S01		HW			
442	P113	10	K	S01		HW			
443	P119	10	K	S01		HW			
444	P120	10	K	S01		HW			
445	U001	10	K	S01		HW			
446	U002	310	K	S01		HW			
447	U003	10	K	S01		HW			

EPA I.D. N	Number <i>(Enter from</i>	Page 1)	Secondary ID Number (Enter from Page 1)					
	NM0890010515							
	ΧI\	/. Description of	Hazardous W	astes (Co	ontinued)			
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)	(1) PROC	(2) PROCESS DESCRIPTION (If a code is not entered in D(1))			
448	U007	10	K	S01		HW		
449	U008	10	K	S01		HW		
450	U009	10	K	S01		HW		
451	U012	10	K	S01		HW		
452	U018	10	K	S01		HW		
453	U019	90	K	S01		HW		
454	U022	10	K	S01		HW		
455	U029	10	К	S01		HW		
456	U031	10	K	S01		HW		
457	U033	10	K	S01		HW		
458	U037	10	K	S01		HW		
459	U041	10	K	S01		HW		
460	U044	10	K	S01		HW		
461	U045	10	K	S01		HW		
462	U052	10	K	S01		HW		
463	U055	10	K	S01		HW		
464	U056	10	K	S01		HW		
465	U057	10	K	S01		HW		
466	U067	10	K	S01		HW		
467	U068	10	K	S01		HW		
468	U070	20	K	S01		HW		
469	U075	50	K	S01		HW		
470	U077	10	K	S01		HW		
471	U080	1,690	K	S01		HW		
472	U085	10	K	S01		HW		
473	U091	180	K	S01		HW		
474	U092	10	K	S01		HW		

EPA I.D. N	Number <i>(Enter from</i>	Page 1)	Secondary ID Number (Enter from Page 1)					
	NM0890010515							
	ΧI\	/. Description of	Hazardous W	astes (Co	ontinued)			
						DDOGESSES		
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)		CESS CODES enter)	(2) PROCESS DESCRIPTION (If a code is not entered in D(1))		
475	U103	10	K	S01		HW		
476	U108	10	K	S01		HW		
477	U109	10	K	S01		HW		
478	U112	10	K	S01		HW		
479	U115	10	K	S01		HW		
480	U117	10	K	S01		HW		
481	U121	10	K	S01		HW		
482	U122	230	K	S01		HW		
483	U123	10	K	S01		HW		
484	U124	10	К	S01		HW		
485	U131	10	K	S01		HW		
486	U133	10	K	S01		HW		
487	U134	180	K	S01		HW		
488	U135	80	K	S01		HW		
489	U136	10	K	S01		HW		
490	U140	10	K	S01		HW		
491	U144	10	K	S01		HW		
492	U145	10	K	S01		HW		
493	U151	240	K	S01		HW		
494	U153	10	K	S01		HW		
495	U154	40	K	S01		HW		
496	U159	20	K	S01		HW		
497	U160	10	K	S01		HW		
498	U161	90	K	S01		HW		
499	U162	10	K	S01		HW		
500	U163	10	K	S01		HW		
501	U165	10	K	S01		HW		

EPA I.D. N	lumber <i>(Enter from</i>		Secondary ID Number (Enter from Page 1)									
I	NM0890010515											
	XI	V. Description of	Hazardous W	Vastes (Continued)								
	A. EPA Hazardous	B. Estimated	C. Unit of	D. PROCESSES								
Line Number	Waste No. (enter code)	Annual Quantity Of Waste	Measure (enter code)	(1) PROCESS CODES (enter)			(2) PROCESS DESCRIPTION (I code is not entered in D(1))					
502	U167	10	K	S01					HW			
503	U168	10	K	S01					HW			
504	U169	10	K	S01					HW			
505	U170	10	K	S01					HW			
506	U188	10	K	S01					HW			
507	U190	10	K	S01				HW				
508	U196	10	K	S01			HW					
509	U204	10	K	S01			HW					
510	U210	100	K	S01				HW				
511	U211	40	K	S01					HW			
512	U213	10	K	S01					HW			
513	U216	10	K	S01					HW			
514	U218	10	К	S01					HW			
515	U219	10	К	S01					HW			
516	U220	100	К	S01					HW			
517	U223	10	К	S01					HW			
518	U225	10	K	S01					HW			
519	U226	2,540	K	S01					HW			
520	U227	10	K	S01 HW								
521	U228	420	K	S01					HW			
522	U239	170	K	S01					HW			
523	U240	10	K	S01					HW			
524	U246	10	K	S01 HW								

EPA I.D. N	lumber <i>(Enter from l</i>	Page 1)		Secondary ID Number (Enter from Page 1)							
NM089001	0515										
XIV. Descrip	otion of Hazardous Wa	astes (Continued))								
				D. PROCESSES							
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)	, ,	CESS CODES	(2) PROCESS DESCRIPTION (If a code is not entered in D(1))					
Technical Area 54 West, Building 38, Container Storage Area											
525	D001	4,210	К	S01		Low-level Mixed Waste (LLMW) and Transuranic Mixed Waste (TRUMW)					
526	D002	2,180	К	S01		LLMW and TRUMW					
527	D003	200	К	S01		LLMW and TRUMW					
528	D004	1,400	К	S01		LLMW and TRUMW					
529	D005	1,280	К	S01		LLMW and TRUMW					
530	D006	205,660	К	S01		LLMW and TRUMW					
531	D007	214,580	K	S01		LLMW and TRUMW					
532	D008	487,000	К	S01		LLMW and TRUMW					
533	D009	14,840	К	S01		LLMW and TRUMW					
534	D010	1,540	K	S01		LLMW and TRUMW					
535	D011	1,720	К	S01		LLMW and TRUMW					
536	D018	80	К	S01		LLMW and TRUMW					
537	D019	1,600	К	S01		LLMW and TRUMW					
538	D021	610	К	S01		LLMW and TRUMW					
539	D022	380	K	S01		LLMW and TRUMW					
540	D027	230	К	S01		LLMW and TRUMW					
541	D028	65,680	K	S01		LLMW and TRUMW					
542	D029	65,350	K	S01		LLMW and TRUMW					
543	D030	1,480	K	S01		LLMW and TRUMW					
544	D031	20	K	S01		LLMW and TRUMW					
545	D032	940	K	S01		LLMW and TRUMW					

EPA I.D. N		Secondary ID Number (Enter from Page 1)														
NM089001	0515															
XIV. Descrip	otion of Hazardous Wa	astes (Continued			<u>_</u>			l l					Į.			
-																
								D.	PR	OCE:	SSE	ES				
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)	(1) PROCESS CODES (enter)			DES	(2) PROCESS DESCRIPTION Code is not entered in E								
546	D033	630	K	S01							LLI	MW a	nd TR	UMV	/	
547	D034	330	K	S01							LLI	MW a	nd TR	UMV	/	
548	D035	30	K	S01							LLI	MW a	nd TR	UMV	/	
549	D036	100	K	S01							LLI	MW a	nd TR	UMV	/	
550	D037	160	K	S01							LLI	MW a	nd TR	UMV	/	
551	D038	20	K	S01							LLI	MW a	nd TR	UMV	/	
552	D039	440	K	S01							LLI	MW a	nd TR	UMV	/	
553	D040	990	K	S01							LLI	MW a	nd TR	UMV	/	
554	D041	20	K	S01							LLI	MW a	nd TR	UMV	/	
555	D042	320	K	S01 LLMW and TRU					UMV	/						
556	D043	120	K	S01							LLI	MW a	nd TR	UMV	/	
557	F001	126,190	K	S01							LLI	MW a	nd TR	UMV	/	
558	F002	16,330	K	S01							LLI	MW a	nd TR	UMV	1	
559	F003	8,270	K	S01							LLI	MW a	nd TR	UMV	1	
560	F004	490	K	S01							LLI	MW a	nd TR	UMV	1	
561	F005	73,530	K	S01							LLI	MW a	nd TR	UMV	/	
562	P003	10	K	S01							LLI	MW a	nd TR	UMV	1	
563	P012	10	K	S01							LLI	MW a	nd TR	UMV	1	
564	P015	10	K	S01							LLI	MW a	nd TR	UMV	/	
565	P029	10	K	S01							LLI	MW a	nd TR	UMV	/	
566	P030	10	K	S01							LLI	MW a	nd TR	UMV	/	
567	P031	10	K	S01							LLI	MW a	nd TR	UMV	/	
568	P038	10	K	S01							LLI	MW a	nd TR	UMV	/	
569	P056	80	K	S01							LLI	MW a	nd TR	UMV	/	
570	P063	10	K	S01							LLI	MW a	nd TR	UMV	/	
571	P068	10	K	S01							LLI	MW a	nd TR	UMV	/	
572	P073	10	K	S01							LLI	MW a	nd TR	UMV	/	

EPA I.D. N	EPA I.D. Number (Enter from Page 1)					Secondary ID Number (Enter from Page 1)									
NM0890010	0515														
XIV. Descrip	tion of Hazardous Wa	astes (Continued)												
					D.	PRO	CES	SSES							
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)	(1) PROCESS CODES (enter)			(2) 1 NOOLOG DEGO								а
573	P076	10	K	S01						LLMV	V an	d TR	UMV	/	
574	P078	10	K	S01						LLMV	V an	d TR	UMV	/	
575	P095	10	K	S01						LLMV	V an	d TR	UMV	/	
576	P096	10	K	S01						LLMV	V an	d TR	UMV	/	
577	P098	10	K	S01						LLMV	V an	d TR	UMV	1	
578	P106	10	K	S01						LLMV	V an	d TR	UMV	1	
579	P113	10	K	S01						LLMV	V an	d TR	UMV	1	
580	P120	10	K	S01						LLMV	V an	d TR	UMV	1	
581	U001	10	K	S01						LLMV	V an	d TR	UMV	/	
582	U002	10	K	S01						LLMV	V an	d TR	UMV	/	
583	U003	10	K	S01						LLMV	V an	d TR	UMV	/	
584	U012	10	K	S01						LLMV	V an	d TR	UMV	/	
585	U019	10	K	S01						LLMV	V an	d TR	UMV	/	
586	U022	10	K	S01						LLMV	V an	d TR	UMV	/	
587	U029	10	K	S01						LLMV	V an	d TR	UMV	/	
588	U031	10	K	S01						LLMV	V an	d TR	UMV	1	
589	U037	10	K	S01						LLMV	V an	d TR	UMV	1	
590	U044	10	K	S01						LLMV	V an	d TR	UMV	1	
591	U045	10	K	S01						LLMV	V an	d TR	UMV	1	
592	U052	10	K	S01						LLMV	V an	d TR	UMV	1	
593	U056	10	K	S01						LLMV	V an	d TR	UMV	1	
594	U057	10	K	S01						LLMV	V an	d TR	UMV	1	
595	U075	10	K	S01						LLMV	V an	d TR	UMV	1	
596	U077	10	K	S01						LLMV	V an	d TR	UMV	1	
597	U080	30	K	S01						LLMV	V an	d TR	UMV	1	
598	U108	10	K	S01						LLMV	V an	d TR	UMV	1	
599	U112	10	K	S01						LLMV	V an	d TR	UMV	1	

EPA I.D. N	EPA I.D. Number (Enter from Page 1)					Secondary ID Number (Enter from Page 1)									
NM089001	0515														
XIV. Descrip	otion of Hazardous Wa	astes (Continued	')		•										
	A. EPA Hazardous		C. Unit of				D.	PR	OCE	SSES	; ——				
Line Number	Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	Measure (enter code)	(1) PROCESS CODES (enter)				CODES (2) PROCESS DESCRIF							
600	U115	10	K	S01						LLM	W ar	nd TR	RUMV	<i>y</i>	
601	U117	10	K	S01						LLM	W ar	nd TR	RUMV	V	
602	U121	10	K	S01						LLM	W ar	nd TR	RUMV	V	
603	U122	10	K	S01						LLM	W ar	nd TR	RUMV	V	
604	U123	10	K	S01						LLM	W ar	nd TR	RUMV	V	
605	U131	10	K	S01						LLM	W ar	nd TR	RUMV	V	
606	U133	10	K	S01						LLM	W ar	nd TR	RUMV	V	
607	U134	10	K	S01						LLM	W ar	nd TR	RUMV	V	
608	U135	10	K	S01						LLM	W ar	nd TR	RUMV	V	
609	U140	10	K	S01						LLM	W ar	nd TR	RUMV	V	
610	U144	10	K	S01						LLM	W ar	nd TR	RUMV	V	
611	U145	10	K	S01						LLM	W ar	nd TR	RUMV	V	
612	U151	60	K	S01						LLM	W ar	nd TR	RUMV	V	
613	U154	20	K	S01						LLM	W ar	nd TR	RUMV	V	
614	U159	30	K	S01						LLM	W ar	nd TR	RUMV	V	
615	U160	10	K	S01						LLM	W ar	nd TR	RUMV	V	
616	U161	10	K	S01						LLM	W ar	nd TR	RUMV	V	
617	U165	10	K	S01						LLM	W ar	nd TR	RUMV	V	
618	U169	10	K	S01						LLM	W ar	nd TR	RUMV	V	
619	U188	10	К	S01						LLM	W ar	nd TR	RUMV	<i>J</i>	
620	U190	10	К	S01						LLM	W ar	nd TR	RUMV	<i>J</i>	
621	U196	10	К	S01						LLM	W ar	nd TR	RUMV	<i>J</i>	
622	U204	10	К	S01						LLM	W ar	nd TR	RUMV	<i>J</i>	
623	U210	10	К	S01						LLM	W ar	nd TR	RUMV	J	
624	U211	10	K	S01						LLM	₩ ar	nd TR	RUMV	<i>J</i>	
625	U213	10	К	S01						LLM	W ar	nd TR	RUMV	J	
626	U216	10	K	S01						LLM	<i>N</i> ar	nd TR	RUMV	<i>J</i>	

EPA I.D. N	Number (Enter from	Page 1)		Secondary ID Number (Enter from Page 1)								
NM089001	0515											
XIV. Descrip	ption of Hazardous Wa	astes (Continued)	•								
D. PROCESSES												
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity Of Waste	C. Unit of Measure (enter code)	(1) PROCESS CODES (2) PROCESS DESCRIPTION (2) code is not entered in E								
627	U218	10	К	S01		LLMW and TRUMW						
628	U219	10	K	S01		LLMW and TRUMW						
629	U220	10	K	S01		LLMW and TRUMW						
630	U225	10	K	S01		LLMW and TRUMW						
631	U226	260	К	S01		LLMW and TRUMW						
632	U227	10	К	S01		LLMW and TRUMW						
633	U228	20	K	S01		LLMW and TRUMW						
634	U239	20	K	S01		LLMW and TRUMW						
635	U246	10	K	S01		LLMW and TRUMW						

EPA I.D. Nu NM08900	mber (enter from Pag 10515	ge 1)		Seconda	ary ID Numb	er (enter from Page 1)
1,1100000						
XIV. Desc	cription of Hazardo	ous Wastes (Co	ntinued)			
Line	A. EPA Hazardous	В.	C. Unit of		D. Pi	rocesses
Number	Waste No. (enter code)	Estimated Annual Quantity of Waste	Measure (enter code)			
				(1) Proce (ent		(2) Process Description (If a code is not entered in D[1])
	Technical Are	ea (TA) 54-226,	-229, -230,	-231, <u>and</u> -2	232 , and Pa	d 10
1	F001	1,301	Р	S01		Transuranic Mixed Waste (TRUMW); A15
2	F002					
3		THIS	LINE INTENTIO	NALLY LEFT I	BLANK	
4	D007	406,940	Р	S01		TRUMW; A25
5	D008					
6		THIS	LINE INTENTIO	NALLY LEFT I	BLANK	
7	D006	311,765	Р	S01		TRUMW; A26
8	D007					
9	D008					
10		THIS	LINE INTENTIO	NALLY LEFT I	BLANK	
11	D001	101,995	Р	S01		TRUMW; A27
12		THIS	LINE INTENTIO	NALLY LEFT I	BLANK	
13	D003	71,062	Р	S01		TRUMW; A28
14		THIS	LINE INTENTIO	NALLY LEFT I	BLANK	
15	D008	96,700	P	S01		TRUMW; A30
16		THIS	LINE INTENTIO	NALLY LEFT I	BLANK	
17	D008	190,691	Р	S01		TRUMW; A31
18		THIS	LINE INTENTIO		BLANK	
19	D008	434,743	Р	S01		TRUMW; A61
20		THIS	LINE INTENTIO	NALLY LEFT I	BLANK	
21	D004	2,413,802	Р	S01		TRUMW; A75
22	D007					
23	D008					
24	D011					
25	F001					
26	F002					
27	F003					
28	F005					

EPA I.D. Nur NM089003	mber (enter from Pag 10515	re 1)		Seco	ndary	ID Numb	er (enter from Page 1)	
XIV. Desc	ription of Hazardo	ous Wastes (Co	ntinued)					
Line Number	A. EPA Hazardous Waste No. (enter code)	B. Estimated Annual Quantity of Waste	C. Unit of Measure (enter code)			D. P	rocesses	
				, ,	ocess (enter)	Codes	(2) Process Description (If a code is not entered in D[1])	
29		THIS	LINE INTENTIO	NALLY LEE	T BLAN	K		
30	D007	313,787	P	S01			TRUMW; A76	
31	F001							
32	F002							
33	33 F005							

EPA I.D. N	umber (Enter from 1	Page 1)		Secondary ID Number (Enter from Page 1)									
<u>N M 0 8</u>	90010	<u>5 1 5</u>											
XIV. Descrip	tion of Hazardous Wa	stes (Continued:	use addition	nal shee	ts as necessary	/)							
	A. EPA	B. Estimated	C. Unit of			PROCESSES							
Line	<u>Hazardous</u>	<u>Annual</u>	<u>Measure</u>	(1) PR	OCESS CODES	(2) PROCESS DESCRIPTION							
<u>Number</u>	<u>Waste No.</u> (enter code)	Quantity Of Waste	<u>(Enter</u> <u>Code)</u>		Enter code)	(If a code is not entered in D(1))							
		<u>Technical</u>	Area 54, Area 0	6, Pad 10									
<u>1</u>	<u>D001</u>	330,000	<u>P</u>	<u>S01</u>									
<u>2</u>	<u>D002</u>	<u>395,000</u>	<u>P</u>	<u>S01</u>									
<u>3</u>	<u>D003</u>	<u>185,000</u>	<u>P</u>	<u>S01</u>									
<u>4</u>	<u>D004</u>	<u>2,525,000</u>	<u>P</u>	<u>S01</u>									
<u>5</u>	<u>D005</u>	<u>82,000</u>	<u>P</u>	<u>S01</u>									
<u>6</u>	<u>D006</u>	<u>515,000</u>	<u>P</u>	<u>S01</u>									
<u>7</u>	<u>D007</u>	<u>3,775,000</u>	<u>P</u>	<u>S01</u>									
<u>8</u>	<u>D008</u>	<u>5,400,000</u>	<u>P</u>	<u>S01</u>									
<u>9</u>	<u>D009</u>	100,000	<u>P</u>	<u>S01</u>									
<u>10</u>	<u>D010</u>	<u>45,000</u>	<u>P</u>	<u>S01</u>									
<u>11</u>	<u>D011</u>	<u>2,540,000</u>	<u>P</u>	<u>S01</u>									
<u>12</u>	<u>D012</u>	<u>18,000</u>	<u>P</u>	<u>S01</u>									
<u>13</u>	<u>D013</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>									
<u>14</u>	<u>D014</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>									
<u>15</u>	<u>D015</u>	7,000	<u>P</u>	<u>S01</u>									
<u>16</u>	<u>D016</u>	4,000	<u>P</u>	<u>S01</u>									
<u>17</u>	<u>D017</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>									
<u>18</u>	<u>D018</u>	30,000	<u>P</u>	<u>S01</u>		-							
<u>19</u>	<u>D019</u>	<u>25,000</u>	<u>P</u>	<u>S01</u>									
<u>20</u>	<u>D020</u>	<u>30,000</u>	<u>P</u>	<u>S01</u>									
<u>21</u>	<u>D021</u>	<u>15,000</u>	<u>P</u>	<u>S01</u>									
<u>22</u>	<u>D022</u>	<u>33,000</u>	<u>P</u>	<u>S01</u>									
<u>23</u>	<u>D023</u>	4,000	<u>P</u>	<u>S01</u>									
<u>24</u>	<u>D024</u>	4,000	<u>P</u>	<u>S01</u>									
<u>25</u>	<u>D025</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>									
<u>26</u>	<u>D026</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>									
<u>27</u>	<u>D027</u>	22,000	<u>P</u>	<u>S01</u>									
<u>28</u>	<u>D028</u>	<u>40,000</u>	<u>P</u>	<u>S01</u>									

EPA I.D. N	umber (Enter from)	Page 1)		Seco	ondary l	D Nur	nber (Enter from Page	<u>1)</u>
N M 0 8	9 0 0 1 0	<u>5 1 5</u>						T
XIV. Descript	tion of Hazardous Wa	stes (Continued:	use addition	nal shee	ts as ned	cessar	v)	
	A. EPA	B. Estimated	C. Unit of				PROCESSES	
<u>Line</u> <u>Number</u>	Hazardous Waste No. (enter code)	Annual Quantity Of Waste	Measure (Enter Code)		ROCESS CO Enter code	<u>ODES</u>	(2) PROCESS DESCRIPTIO	_
•		Technical Area	54, Area G, Pad	10 (Contir	nued)			
29	D029	7,000	Р	<u>S01</u>				
30	D030	30,000	<u>-</u> Р	S01				
31	D031	22,000	<u></u> Р	S01				
<u>32</u>	D032	29,000	P	<u>S01</u>				
33	D033	29,000	<u>–</u> Р	<u>S01</u>				
<u>34</u>	<u>D034</u>	29,000	<u>-</u> <u>Р</u>	<u>S01</u>				
<u>35</u>	<u>D035</u>	30,000	<u>Р</u>	<u>S01</u>				
36	D036	19,000	P	S01				
37	D037	7,000	P	S01				
38	<u>D038</u>	14,000	<u>Р</u>	<u>S01</u>				
<u>39</u>	<u>D039</u>	20,000	<u>Р</u>	<u>S01</u>				
40	<u>D040</u>	<u>25,000</u>	<u>Р</u>	<u>S01</u>				
41	<u>D041</u>	17,000	<u>P</u>	<u>S01</u>				
42	D042	22,000	<u>P</u>	<u>S01</u>				
<u>43</u>	<u>D043</u>	<u>25,000</u>	<u>P</u>	<u>S01</u>				
44	<u>F001</u>	6,410,000	<u>P</u>	<u>S01</u>				
<u>45</u>	<u>F002</u>	<u>3,450,000</u>	<u>P</u>	<u>S01</u>				
<u>46</u>	<u>F003</u>	<u>2,850,000</u>	<u>P</u>	<u>S01</u>				
<u>47</u>	<u>F004</u>	<u>35,000</u>	<u>P</u>	<u>S01</u>				
<u>48</u>	<u>F005</u>	3,250,000	<u>P</u>	<u>S01</u>				
<u>49</u>	<u>F006</u>	<u>7,000</u>	<u>P</u>	<u>S01</u>				
<u>50</u>	<u>F007</u>	<u>18,000</u>	<u>P</u>	<u>S01</u>				
<u>51</u>	<u>F008</u>	<u>7,000</u>	<u>P</u>	<u>S01</u>				
<u>52</u>	<u>F009</u>	<u>8,000</u>	<u>P</u>	<u>S01</u>				
<u>53</u>	<u>F010</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>54</u>	<u>F011</u>	4,000	<u>P</u>	<u>S01</u>				
<u>55</u>	<u>F012</u>	4,000	<u>P</u>	<u>S01</u>				
<u>56</u>	<u>F019</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>57</u>	<u>F020</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>58</u>	<u>F021</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				

EPA I.D. N	umber (Enter from 1	Page 1)		Seco	ondary 1	ID Nui	mber (Enter f	rom Page 1)
N M 0 8	90010	<u>5 1 5</u>						
XIV. Descrip	otion of Hazardous Wa	stes (Continued:	use addition	nal shee	ets as ne	cessar	v)	
	A. EPA	B. Estimated	C. Unit of				PROCESSES	
<u>Line</u> Number	<u>Hazardous</u> Waste No.	<u>Annual</u> Quantity	Measure (Enter	(1) PF	ROCESS C			DESCRIPTION
<u>Number</u>	<u>waste No.</u> (enter code)	Of Waste	<u>(Enter</u> <u>Code)</u>		Enter code			t entered in D(1))
		Technical Area	54, Area G, Pad	10 (Conti	nued)			
<u>59</u>	<u>F022</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>60</u>	<u>F023</u>	4,000	<u>P</u>	<u>S01</u>				
<u>61</u>	<u>F024</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>62</u>	<u>F025</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>63</u>	<u>F026</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>64</u>	<u>F027</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>65</u>	<u>F028</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>66</u>	<u>F032</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>67</u>	<u>F034</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>68</u>	<u>F035</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>69</u>	<u>F037</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>70</u>	<u>F038</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>71</u>	<u>F039</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>72</u>	<u>K044</u>	<u>22,000</u>	<u>P</u>	<u>S01</u>				
<u>73</u>	<u>K045</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>74</u>	<u>K046</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>75</u>	<u>K047</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>76</u>	<u>K084</u>	<u>500</u>	<u>P</u>	<u>S01</u>				
<u>77</u>	<u>K101</u>	<u>500</u>	<u>P</u>	<u>S01</u>				
<u>78</u>	<u>K102</u>	<u>500</u>	<u>P</u>	<u>S01</u>				
<u>79</u>	<u>P001</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>80</u>	<u>P002</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>81</u>	<u>P003</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>82</u>	<u>P004</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>83</u>	<u>P005</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>84</u>	<u>P006</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>85</u>	<u>P007</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>86</u>	<u>P008</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>87</u>	<u>P009</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>88</u>	<u>P010</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				

EPA I.D. N	umber (Enter from 1	Page 1)		Seco	ondary l	D Nui	mber (Enter	from Page 1)
N M 0 8	90010	<u>5 1 5</u>						
XIV. Descrip	tion of Hazardous Wa	stes (Continued:	use addition	nal shee	ets as ne	cessar	v)	
	A. EPA	B. Estimated	C. Unit of				PROCESSES	
<u>Line</u> Number	<u>Hazardous</u> Waste No.	<u>Annual</u> Quantity	Measure (Enter	(1) PF	ROCESS CO			S DESCRIPTION
<u>Number</u>	<u>waste No.</u> (enter code)	Of Waste	<u>(Enter</u> <u>Code)</u>		Enter code		· ·	ot entered in D(1))
		Technical Area	54, Area G, Pad	10 (Conti	nued)			
<u>89</u>	<u>P011</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>90</u>	<u>P012</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>91</u>	<u>P013</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>92</u>	<u>P014</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>93</u>	<u>P015</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>94</u>	<u>P016</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>95</u>	<u>P017</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>96</u>	<u>P018</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>97</u>	<u>P020</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>98</u>	<u>P021</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>99</u>	<u>P022</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>100</u>	<u>P023</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>101</u>	<u>P024</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>102</u>	<u>P026</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>103</u>	<u>P027</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>104</u>	<u>P028</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>105</u>	<u>P029</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>106</u>	<u>P030</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>107</u>	<u>P031</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>108</u>	<u>P033</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>109</u>	<u>P034</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>110</u>	<u>P036</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>111</u>	<u>P037</u>	4,000	<u>P</u>	<u>S01</u>				
<u>112</u>	<u>P038</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>113</u>	<u>P039</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>114</u>	<u>P040</u>	4,000	<u>P</u>	<u>S01</u>				
<u>115</u>	<u>P041</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>116</u>	<u>P042</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>117</u>	<u>P043</u>	4,000	<u>P</u>	<u>S01</u>				
<u>118</u>	<u>P044</u>	4,000	<u>P</u>	<u>S01</u>				

EPA I.D. N	umber (Enter from 1	Page 1)		Seco	ondary	ID Nur	mber (Enter from Page 1)
N M 0 8	9 0 0 1 0 9	5 1 5					
XIV. Descrip	tion of Hazardous Wa	 , ,	use addition	nal shee	ts as ne	ecessar	v)
	<u>A. EPA</u>	B. Estimated	C. Unit of				PROCESSES
<u>Line</u>	Hazardous	<u>Annual</u>	<u>Measure</u>	(1) PROCESS CODES			(2) PROCESS DESCRIPTION
<u>Number</u>	<u>Waste No.</u> (enter code)	<u>Quantity</u> <u>Of Waste</u>	<u>(Enter</u> Code)		Enter cod		(If a code is not entered in D(1))
		Technical Area	54, Area G, Pad	10 (Contir	nued)		
119	P045	4,000	Р	<u>S01</u>			
120	P046	4,000	<u>.</u> Р	S01			
<u>121</u>	P047	4,000	<u>.</u> Р	S01			
122	P048	4,000	P	S01			
123	<u>P049</u>	4,000	<u>–</u> Р	S01			
124	P050	4,000	P	<u>S01</u>			
125	P051	4,000	<u>–</u> <u>Р</u>	<u>S01</u>			
126	<u>P054</u>	4,000	<u>P</u>	<u>S01</u>			
127	<u>P056</u>	4,100	<u>P</u>	<u>S01</u>			
<u>128</u>	<u>P057</u>	4,000	<u>P</u>	<u>S01</u>			
<u>129</u>	<u>P058</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>			
<u>130</u>	<u>P059</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>			
<u>131</u>	<u>P060</u>	4,000	<u>P</u>	<u>S01</u>			
<u>132</u>	<u>P062</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>			
<u>133</u>	<u>P063</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>			
<u>134</u>	<u>P064</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>			
<u>135</u>	<u>P065</u>	4,000	<u>P</u>	<u>S01</u>			
<u>136</u>	<u>P066</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>			
<u>137</u>	<u>P067</u>	4,000	<u>P</u>	<u>S01</u>			
<u>138</u>	<u>P068</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>			
<u>139</u>	<u>P069</u>	4,000	<u>P</u>	<u>S01</u>			
<u>140</u>	<u>P070</u>	4,000	<u>P</u>	<u>S01</u>			
<u>141</u>	<u>P071</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>			
<u>142</u>	<u>P072</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>			
<u>143</u>	<u>P073</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>			
<u>144</u>	<u>P074</u>	4,000	<u>P</u>	<u>S01</u>			
<u>145</u>	<u>P075</u>	4,000	<u>P</u>	<u>S01</u>			
<u>146</u>	<u>P076</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>			
<u>147</u>	<u>P077</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>			
<u>148</u>	<u>P078</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>			

EPA I.D. N	umber (Enter from 1	Page 1)		Secondary ID Number (Enter from Page 1)				
N M 0 8	9 0 0 1 0 9	5 1 5						
XIV. Descript	tion of Hazardous Wa	 , ,	use addition	nal shee	ets as ne	ecessar	v)	
,, <u></u>	A. EPA	B. Estimated	C. Unit of	D. PROCESSES				
<u>Line</u>	<u>Hazardous</u>	<u>Annual</u>	<u>Measure</u>	(1) DE	ROCESS C		(2) PROCESS DESCRIPTION	
<u>Number</u>	<u>Waste No.</u> (enter code)	<u>Quantity</u> <u>Of Waste</u>	<u>(Enter</u> Code)		Enter cod		(If a code is not entered in D(1))	
_		Technical Area	54, Area G, Pad	10 (Conti	nued)			
149	P081	4,000	Р	<u>S01</u>				
150	P082	4,000	<u>.</u> Р	S01				
<u>151</u>	P084	4,000	<u>.</u> Р	S01				
<u>152</u>	P085	4,000	P	S01				
153	P087	4,000	<u></u> Р	S01				
<u>154</u>	P088	4,000	<u>–</u> Р	<u>S01</u>				
155	P089	4,000	<u>–</u> Р	S01				
156	P092	4,000	P	<u>S01</u>				
157	P093	4,000	P	<u>S01</u>				
158	P094	4,000	P	S01				
<u>159</u>	P095	4,100	<u>Р</u>	<u>S01</u>				
<u>160</u>	<u>P096</u>	4,100	<u>Р</u>	<u>S01</u>				
<u>161</u>	P097	4,000	<u>Р</u>	<u>S01</u>				
<u>162</u>	P098	4,100	<u>P</u>	<u>S01</u>				
<u>163</u>	P099	4,000	<u>P</u>	<u>S01</u>				
164	P101	4,000	<u>P</u>	<u>S01</u>				
<u>165</u>	P102	4,000	<u>Р</u>	<u>S01</u>				
<u>166</u>	<u>P103</u>	4,000	<u>P</u>	<u>S01</u>				
<u>167</u>	<u>P104</u>	4,000	<u>P</u>	<u>S01</u>				
<u>168</u>	<u>P105</u>	4,000	<u>Р</u>	<u>S01</u>				
<u>169</u>	<u>P106</u>	4,100	<u>P</u>	<u>S01</u>				
<u>170</u>	<u>P108</u>	4,000	<u>P</u>	<u>S01</u>				
<u>171</u>	<u>P109</u>	4,000	<u>P</u>	<u>S01</u>				
<u>172</u>	<u>P110</u>	4,000	<u>P</u>	<u>S01</u>				
<u>173</u>	<u>P111</u>	4,000	<u>Р</u>	<u>S01</u>				
<u>174</u>	<u>P112</u>	4,000	<u>P</u>	<u>S01</u>				
<u>175</u>	<u>P113</u>	4,100	<u>P</u>	<u>S01</u>				
<u>176</u>	<u>P114</u>	4,000	<u>P</u>	<u>S01</u>				
<u>177</u>	<u>P115</u>	4,000	<u>P</u>	<u>S01</u>				
<u>178</u>	<u>P116</u>	4,000	<u>P</u>	<u>S01</u>				

EPA I.D. N	umber (Enter from 1	Page 1)		Secondary ID Number (Enter from Page 1)				
N M 0 8	90010	<u>5 1 5</u>						
XIV. Descrip	otion of Hazardous Wa		use addition	nal shee	ts as ne	cessar	v)	
	A. EPA	B. Estimated	C. Unit of				PROCESSES	
<u>Line</u>	<u>Hazardous</u>	<u>Annual</u>	<u>Measure</u>	(1) DD	OCESS C		(2) PROCESS DESCRIPTION	
<u>Number</u>	<u>Waste No.</u> (enter code)	<u>Quantity</u> <u>Of Waste</u>	<u>(Enter</u> Code)		Enter code		(If a code is not entered in D(1))	
		Technical Area	54, Area G, Pad	10 (Contin	ued)			
179	P118	4,000	Р	S01				
180	P119	4,000	P	S01				
181	P120	4,100	Р	S01				
182	<u>P121</u>	4,000	<u>Р</u>	S01				
<u>183</u>	<u>P122</u>	4,000	<u>Р</u>	<u>S01</u>				
<u>184</u>	<u>P123</u>	4,000	<u>Р</u>	<u>S01</u>				
<u>185</u>	<u>P127</u>	4,000	<u>P</u>	<u>S01</u>				
<u>186</u>	<u>P128</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>187</u>	<u>P185</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>188</u>	<u>P188</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>189</u>	<u>P189</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>190</u>	<u>P190</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>191</u>	<u>P191</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>192</u>	<u>P192</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>193</u>	<u>P194</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>194</u>	<u>P196</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>195</u>	<u>P197</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>196</u>	<u>P198</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>197</u>	<u>P199</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>198</u>	<u>P201</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>199</u>	<u>P202</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>200</u>	<u>P203</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>201</u>	<u>P204</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>202</u>	<u>P205</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>203</u>	<u>U001</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>204</u>	<u>U002</u>	<u>7,100</u>	<u>P</u>	<u>S01</u>				
<u>205</u>	<u>U003</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>206</u>	<u>U004</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>207</u>	<u>U005</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>208</u>	<u>U006</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				

EPA I.D. Nu	mber (Enter from	Page 1)		Secondary ID Number (Enter from Page 1)					
N M 0 8	9 0 0 1 0	<u>5 1 5</u>							
XIV. Descripti	on of Hazardous Wa	astes (Continued:	: use additio	nal shee	ts as necessa	rv)			
	<u>A. EPA</u>	B. Estimated	C. Unit of	D. PROCESSES					
<u>Line</u>	<u>Hazardous</u>	<u>Annual</u>	<u>Measure</u>	(1) DD	OCESS CODES	(2) PROCESS DESCRIPTION			
<u>Number</u>	<u>Waste No.</u> (enter code)	<u>Quantity</u> <u>Of Waste</u>	<u>(Enter</u> <u>Code)</u>		Enter code)	(If a code is not entered in D(1))			
		Technical Area	54, Area G, Pad	10 (Contin	<u>ued)</u>				
209	U007	4,000	Р	<u>S01</u>					
210	U008	4,000	P	S01					
211	<u>U009</u>	4,000	P	S01					
<u>212</u>	U010	4,000	Р	<u>S01</u>					
<u>213</u>			_						
	<u>U011</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>214</u>	<u>U012</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>					
<u>215</u>	<u>U014</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>216</u>	<u>U015</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>217</u>	<u>U016</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>218</u>	<u>U017</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>219</u>	<u>U018</u>	4,000	<u>P</u>	<u>S01</u>					
<u>220</u>	<u>U019</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>					
<u>221</u>	<u>U020</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
222	<u>U021</u>	4,000	<u>Р</u>	<u>S01</u>					
223	<u>U022</u> U023	<u>4,100</u>	<u>Р</u> Р	<u>S01</u>		†			
<u>224</u> <u>225</u>	<u>U023</u>	<u>4,000</u> 4,000	<u>Р</u> Р	<u>S01</u> <u>S01</u>					
226	<u>U025</u>	4,000	<u>-</u> Р	<u>S01</u>					
<u>227</u>	<u>U026</u>	4,000	<u>г</u> <u>Р</u>	<u>S01</u>					
<u>228</u>	<u>U027</u>	4,000	<u>г</u> Р	<u>501</u>					
<u>229</u>	<u>U028</u>	4,000	<u>.</u> Р	<u>S01</u>		1			
230	<u>U029</u>	4,100	<u>-</u> <u>Р</u>	<u>S01</u>					
231	<u>U030</u>	4,000	<u>-</u> Р	S01					
<u>232</u>	<u>U031</u>	4,100	<u>Р</u>	<u>S01</u>					
<u>233</u>	<u>U032</u>	4,000	<u>Р</u>	<u>S01</u>					
<u>234</u>	<u>U033</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>235</u>	<u>U034</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>236</u>	<u>U035</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>237</u>	<u>U036</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					

EPA I.D. N	umber (Enter from 1	Page 1)		Secondary ID Number (Enter from Page 1)				
N M 0 8	90010	5 1 5						
XIV. Descrip	otion of Hazardous Wa		use addition	nal shee	ts as ne	cessar	v)	
	A. EPA	B. Estimated	C. Unit of				PROCESSES	
<u>Line</u>	<u>Hazardous</u>	<u>Annual</u>	<u>Measure</u>	(1) DD	OCESS C		(2) PROCESS DESCRIPTION	
<u>Number</u>	<u>Waste No.</u> (enter code)	<u>Quantity</u> <u>Of Waste</u>	<u>(Enter</u> Code)		Enter code		(If a code is not entered in D(1))	
		Technical Area	54, Area G, Pad	10 (Contin	ued)			
238	U037	4,100	Р	S01				
239	U038	4,000	P	S01				
240	<u>U039</u>	4,000	Р	S01				
241	<u>U041</u>	4,000	<u>Р</u>	<u>S01</u>				
<u>242</u>	<u>U042</u>	4,000	<u> Р</u>	<u>S01</u>				
<u>243</u>	<u>U043</u>	4,000	<u> Р</u>	<u>S01</u>				
244	<u>U044</u>	4,100	<u>P</u>	<u>S01</u>				
<u>245</u>	<u>U045</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>246</u>	<u>U046</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>247</u>	<u>U047</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>248</u>	<u>U048</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>249</u>	<u>U049</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>250</u>	<u>U050</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>251</u>	<u>U051</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>252</u>	<u>U052</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>253</u>	<u>U053</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>254</u>	<u>U055</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>255</u>	<u>U056</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>256</u>	<u>U057</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>257</u>	<u>U058</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>258</u>	<u>U059</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>259</u>	<u>U060</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>260</u>	<u>U061</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>261</u>	<u>U062</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>262</u>	<u>U063</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>263</u>	<u>U064</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>264</u>	<u>U066</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>265</u>	<u>U067</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>266</u>	<u>U068</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>267</u>	<u>U069</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				

EPA I.D. N	umber (Enter from 1	Page 1)		Secondary ID Number (Enter from Page 1)					
N M 0 8	9 0 0 1 0 5	5 1 5							
XIV. Descrip	tion of Hazardous Wa		use addition	nal shee	ets as ne	ecessar	v)		
	<u>A. EPA</u>	B. Estimated	C. Unit of	D. PROCESSES					
<u>Line</u>	<u>Hazardous</u>	<u>Annual</u>	<u>Measure</u>	(1) DE	ROCESS ((2) PROCESS DESCRIPTION		
<u>Number</u>	<u>Waste No.</u> (enter code)	<u>Quantity</u> <u>Of Waste</u>	<u>(Enter</u> Code)		Enter cod		(If a code is not entered in D(1))		
		Technical Area	54, Area G, Pad	10 (Conti	nued)				
<u>268</u>	U070	4,000	Р	<u>S01</u>					
269	U071	4,000	<u>.</u> Р	S01					
270	U072	4,000	<u>.</u> Р	S01					
271	<u>U073</u>	4,000	P	S01					
272	<u>557.5</u> U074	4,000	<u></u> Р	S01					
273	<u>U075</u>	4,100	<u>–</u> Р	<u>S01</u>					
274	<u></u> U076	4,000	<u>–</u> Р	S01					
275	U077	4,100	P	<u>S01</u>					
<u>276</u>	U078	4,000	P	<u>S01</u>					
277	U079	4,000	P	S01					
278	<u>U080</u>	12,000	<u>Р</u>	<u>S01</u>					
279	<u>U081</u>	4,000	<u>Р</u>	<u>S01</u>					
280	<u>U</u> 082	4,000	<u>Р</u>	<u>S01</u>					
<u>281</u>	<u>U083</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>282</u>	<u>U084</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>283</u>	<u>U085</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>284</u>	<u>U086</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>285</u>	<u>U087</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>286</u>	<u>U088</u>	4,000	<u>P</u>	<u>S01</u>					
<u>287</u>	<u>U089</u>	4,000	<u>P</u>	<u>S01</u>					
<u>288</u>	<u>U090</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>289</u>	<u>U091</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>290</u>	<u>U092</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>291</u>	<u>U093</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>292</u>	<u>U094</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>293</u>	<u>U095</u>	4,000	<u>P</u>	<u>S01</u>					
<u>294</u>	<u>U096</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>295</u>	<u>U097</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>296</u>	<u>U098</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					
<u>297</u>	<u>U099</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>					

EPA I.D. N	umber (Enter from 1	Page 1)		Secondary ID Number (Enter from Page 1)				
N M 0 8	90010	5 1 5						
XIV. Descrip	tion of Hazardous Wa	stes (Continued:	use addition	nal shee	ts as ne	cessar	v)	
	<u>A. EPA</u>	B. Estimated	C. Unit of				PROCESSES	
<u>Line</u>	<u>Hazardous</u>	<u>Annual</u>	<u>Measure</u>	(1) PR	OCESS C		(2) PROCESS DESCRIPTION	
<u>Number</u>	<u>Waste No.</u> (enter code)	<u>Quantity</u> <u>Of Waste</u>	<u>(Enter</u> <u>Code)</u>		Inter code		(If a code is not entered in D(1))	
		Technical Area	54, Area G, Pad	10 (Contin	ued)			
298	U101	4,000	Р	S01				
299	U102	4,000	P	S01				
300	<u>U103</u>	4,000	P	<u>S01</u>				
<u>301</u>	<u>U105</u>	4,000	<u>P</u>	<u>S01</u>				
302	<u>U106</u>	4,000	<u>Р</u>	<u>S01</u>				
<u>303</u>	<u>U107</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>304</u>	<u>U108</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>	-			
<u>305</u>	<u>U109</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>306</u>	<u>U110</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>307</u>	<u>U111</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>308</u>	<u>U112</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>309</u>	<u>U113</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>310</u>	<u>U114</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>311</u>	<u>U115</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>312</u>	<u>U116</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>313</u>	<u>U117</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>314</u>	<u>U118</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>315</u>	<u>U119</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>316</u>	<u>U120</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>317</u>	<u>U121</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>318</u>	<u>U122</u>	<u>7,100</u>	<u>P</u>	<u>S01</u>				
<u>319</u>	<u>U123</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>320</u>	<u>U124</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>321</u>	<u>U125</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>322</u>	<u>U126</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>323</u>	<u>U127</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>324</u>	<u>U128</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>325</u>	<u>U129</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>326</u>	<u>U130</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>327</u>	<u>U131</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				

EPA I.D. N	umber (Enter from 1	Page 1)		Secondary ID Number (Enter from Page 1)				
N M 0 8	9 0 0 1 0 5	5 1 5				T		
XIV. Descrip	tion of Hazardous Wa		use addition	nal shee	ets as ne	ecessar	v)	
	<u>A. EPA</u>	B. Estimated	C. Unit of	D. PROCESSES				
Line	<u>Hazardous</u>	<u>Annual</u>	<u>Measure</u>	(1) PF	ROCESS C		(2) PROCESS DESCRIPTION	
<u>Number</u>	<u>Waste No.</u> (enter code)	<u>Quantity</u> Of Waste	<u>(Enter</u> <u>Code)</u>		Enter cod		(If a code is not entered in D(1))	
		Technical Area	54, Area G, Pad	10 (Conti	nued)			
<u>328</u>	U132	4,000	Р	<u>S01</u>				
329	<u>U133</u>	4,100	P	S01				
330	<u>U134</u>	12,100	<u>Р</u>	<u>S01</u>				
<u>331</u>	<u>U135</u>	4,100	<u>P</u>	<u>S01</u>				
332	<u>U136</u>	4,000	<u>Р</u>	<u>S01</u>				
<u>333</u>	<u>U137</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>334</u>	<u>U138</u>	4,000	<u>P</u>	<u>S01</u>				
<u>335</u>	<u>U140</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>336</u>	<u>U141</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>337</u>	<u>U142</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>338</u>	<u>U143</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>339</u>	<u>U144</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>340</u>	<u>U145</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>341</u>	<u>U146</u>	4,000	<u>P</u>	<u>S01</u>				
<u>342</u>	<u>U147</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>343</u>	<u>U148</u>	4,000	<u>P</u>	<u>S01</u>				
<u>344</u>	<u>U149</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>345</u>	<u>U150</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>346</u>	<u>U151</u>	<u>7,100</u>	<u>P</u>	<u>S01</u>				
<u>347</u>	<u>U152</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>		1		
<u>348</u>	<u>U153</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>		1		
<u>349</u>	<u>U154</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>		1		
<u>350</u>	<u>U155</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>		1		
<u>351</u>	<u>U156</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>352</u>	<u>U157</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>353</u>	<u>U158</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>		1		
<u>354</u>	<u>U159</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>355</u>	<u>U160</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>356</u>	<u>U161</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>357</u>	<u>U162</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				

EPA I.D. N	umber (Enter from)	Page 1)		Secondary ID Number (Enter from Page 1)						
N M 0 8	90010	<u>5 1 5</u>								
XIV. Descrip	tion of Hazardous Wa	stes (Continued:	use addition	nal shee	ts as necessar	/)				
	A. EPA	B. Estimated	C. Unit of			PROCESSES				
<u>Line</u>	<u>Hazardous</u>	<u>Annual</u>	<u>Measure</u>	(1) PR	OCESS CODES	(2) PROCESS DESCRIPTION				
<u>Number</u>	<u>Waste No.</u> (enter code)	<u>Quantity</u> <u>Of Waste</u>	<u>(Enter</u> <u>Code)</u>		Enter code)	(If a code is not entered in D(1))				
		Technical Area	54, Area G, Pad	10 (Contir	nued)					
358	U163	4,000	Р	S01						
359	<u>U164</u>	4,000	<u>Р</u>	S01						
360	 U165	4,100	<u> </u>	S01						
361	<u>U166</u>	4,000	<u>. </u>	S01						
362	<u>U167</u>	4,000	<u>-</u> Р	S01						
363	<u>U168</u>	4,000	<u>. </u>	S01						
<u>364</u>	<u>U169</u>	4,100	<u>-</u> Р	<u>S01</u>						
365	U170	4,000	<u>–</u> Р	S01						
<u>366</u>	<u>U171</u>	4,000	— <u>—</u> Р	<u>S01</u>						
367	<u>U172</u>	4,000	<u>–</u> Р	S01						
<u>368</u>	<u>U173</u>	4,000	P	<u>S01</u>						
369	U174	4,000	P	S01						
<u>370</u>	<u>U176</u>	4,000	<u>Р</u>	<u>S01</u>						
<u>371</u>	<u>U177</u>	4,000	<u>P</u>	<u>S01</u>						
<u>372</u>	<u>U178</u>	4,000	<u>P</u>	<u>S01</u>						
<u>373</u>	<u>U179</u>	4,000	<u>P</u>	<u>S01</u>						
<u>374</u>	<u>U180</u>	4,000	<u>P</u>	<u>S01</u>						
<u>375</u>	<u>U181</u>	4,000	<u>P</u>	<u>S01</u>						
<u>376</u>	<u>U182</u>	4,000	<u>P</u>	<u>S01</u>						
<u>377</u>	<u>U183</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>						
<u>378</u>	<u>U184</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>						
<u>379</u>	<u>U185</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>						
<u>380</u>	<u>U186</u>	4,000	<u>P</u>	<u>S01</u>						
<u>381</u>	<u>U187</u>	4,000	<u>P</u>	<u>S01</u>						
<u>382</u>	<u>U188</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>						
<u>383</u>	<u>U189</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>						
<u>384</u>	<u>U190</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>						
<u>385</u>	<u>U191</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>						
<u>386</u>	<u>U192</u>	4,000	<u>Р</u>	<u>S01</u>						

EPA I.D. N	umber (Enter from 1	Page 1)		Secondary ID Number (Enter from Page 1)				
N M 0 8	90010	<u>5 1 5</u>						
XIV. Descrip	tion of Hazardous Wa	stes (Continued:	use addition	nal shee	ts as ne	cessar	v)	
	<u>A. EPA</u>	B. Estimated	C. Unit of	D. PROCESSES				
<u>Line</u> Number	<u>Hazardous</u> Waste No.	Annual Quantity	Measure (Enter	(1) PF	ROCESS C	ODES	(2) PROCE	SS DESCRIPTION
<u>Number</u>	(enter code)	Of Waste	<u>Code</u>)		Enter code		(If a code is	not entered in D(1))
		Technical Area	54, Area G, Pad	10 (Contii	nued)			
<u>387</u>	<u>U193</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>388</u>	<u>U194</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>389</u>	<u>U196</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>390</u>	<u>U197</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>391</u>	<u>U200</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>392</u>	<u>U201</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>393</u>	<u>U202</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>394</u>	<u>U203</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>395</u>	<u>U204</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>396</u>	<u>U205</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>397</u>	<u>U206</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>398</u>	<u>U207</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>399</u>	<u>U208</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>400</u>	<u>U209</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>401</u>	<u>U210</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>402</u>	<u>U211</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>403</u>	<u>U213</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>404</u>	<u>U214</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>405</u>	<u>U215</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>406</u>	<u>U216</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>407</u>	<u>U217</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>408</u>	<u>U218</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>409</u>	<u>U219</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>410</u>	<u>U220</u>	<u>7,100</u>	<u>P</u>	<u>S01</u>				
<u>411</u>	<u>U221</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>412</u>	<u>U222</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>413</u>	<u>U223</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>414</u>	<u>U225</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
<u>415</u>	<u>U226</u>	<u>7,100</u>	<u>P</u>	<u>S01</u>				

EPA I.D. N	umber (Enter from 1	Page 1)		Secondary ID Number (Enter from Page 1)				
N M 0 8	90010	5 <u>1 5</u>						
XIV. Descrip	tion of Hazardous Wa	stes (Continued;	use addition	nal sheet	ts as necessary	<u>d</u>		
	A. EPA	B. Estimated	C. Unit of	D. PROCESSES				
<u>Line</u> <u>Number</u>	<u>Hazardous</u> <u>Waste No.</u>	<u>Annual</u> <u>Quantity</u>	<u>Measure</u> <u>(Enter</u>		OCESS CODES	(2) PROCESS DESCRIPTION		
	(enter code)	Of Waste	<u>Code</u>)		Enter code)	(If a code is not entered in D(1))		
		Technical Area	54, Area G, Pad	10 (Contin	ued)			
<u>416</u>	<u>U227</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
417	<u>U228</u>	<u>7,100</u>	<u>P</u>	<u>S01</u>				
<u>418</u>	<u>U234</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>419</u>	<u>U235</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>420</u>	<u>U236</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>421</u>	<u>U237</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>422</u>	<u>U238</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
423	<u>U239</u>	<u>7,100</u>	<u>P</u>	<u>S01</u>				
<u>424</u>	<u>U240</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>425</u>	<u>U243</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>426</u>	<u>U244</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>427</u>	<u>U246</u>	<u>4,100</u>	<u>P</u>	<u>S01</u>				
428	<u>U247</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>429</u>	<u>U248</u>	4,000	<u>P</u>	<u>S01</u>				
<u>430</u>	<u>U249</u>	4,000	<u>P</u>	<u>S01</u>				
<u>431</u>	<u>U271</u>	4,000	<u>P</u>	<u>S01</u>				
<u>432</u>	<u>U278</u>	4,000	<u>P</u>	<u>S01</u>				
433	<u>U279</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
434	<u>U280</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
435	<u>U328</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
436	<u>U353</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
437	<u>U359</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
438	<u>U364</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>439</u>	<u>U367</u>	4,000	<u>P</u>	<u>S01</u>				
<u>440</u>	<u>U372</u>	4,000	<u>P</u>	<u>S01</u>				
<u>441</u>	<u>U373</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
<u>442</u>	<u>U387</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				

		umber (Enter from 1			Secondary ID Number (Enter from Page 1)				
	N M 0 8	<u> </u>	<u>5 1 5 </u>						
	XIV. Descrip	tion of Hazardous Wa	stes (Continued;	use addition	al sheets a	as necessary	<u>()</u>		
<u> </u>						PROCESSES			
	<u>Line</u> <u>Number</u>	Hazardous Waste No.	Annual Quantity Of Wasto	<u>Measure</u> (Enter		ESS CODES er code)	(2) PROCESS DESCRIPTION (If a code is not entered in D(1))		
 	(enter code) Of Waste Code) (If a code is not entered in D(1)) Technical Area 54, Area G, Pad 10 (Continued)								
			Technical Area 3	54, Area G, Pau	io (Continued	<u> </u>			
	<u>443</u>	<u>U389</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
	<u>444</u>	<u>U394</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
	<u>445</u>	<u>U395</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
	<u>446</u>	<u>U404</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
	<u>447</u>	<u>U409</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
	<u>448</u>	<u>U410</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				
	<u>449</u>	<u>U411</u>	<u>4,000</u>	<u>P</u>	<u>S01</u>				